

CH4ZTL

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	98604 KM
File nr. :	1434129	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FMG899 / WDD2462001J173964 /		yr of constructionr :	/
E-File nr. :		First registration :	16/08/2013
VFS-nr. :		Color :	BROWN
Make + Model :	MERCEDES / B	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :	N	Environment Class:	EURO 5
Customer company :	PROXIMUS	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1796
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	109	kW:	80
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	[x]
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :	[x]	Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	[x]	Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	DUNLOP	Tyre :	OK	4-6/	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel RL :	DUNLOP	Tyre :	OK	4-6/	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel FR :	DUNLOP	Tyre :	OK	4-6/	Rim :	/	Hubcap :	SCRATCHED
Wheel RR :	DUNLOP	Tyre :	OK	4-6/	Rim :	/	Hubcap :	SCRATCHED
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	H
Rear tyre	195	65	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE		
[x]	REAR MUDGUARD/LEFT/FRONT	DENT		
[x]	REAR WINDOW/LEFT	SCRATCH WITH PAINT DAMAGE		
[x]	ROOF/CENTER/LEFT	OTHER DAMAGES	TE POLIJSTEN	

Interior

[x]	SEAT FL	STAIN		
[x]	SEAT FR	STAIN		

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/FRONT	DENT				
	Number	Code	Description	Unit price	Depr.	Total
	3	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT BUMPER/CENTER/RIGHT	DENT				
			Repair paint - LI	New paint - E	Depr.	Total
	2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Interior

[x]	SEAT REAR L	STAIN				
	Number	Code	Description	Unit price	Depr.	Total
	1	I 1 i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR

Others

	HUB CAP FL					
			Repair paint - LI	New paint - E	Depr.	Total
	4	0 LU =0.00 EUR			50 %	

Pieces

	Number	Code	Description	Unit price	Depr.	Total
	4	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
14.58	211.80	63.00	30.00	0	0	0	0	0	0
14.58	105.90	63.00	15.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
77.58	241.80	0	319.38
HOG: 0	BG: 0		NA Deprec. 198.48
			0.00%
			TOTAL 198.48

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 08/09/2017 Hour : 13:03 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	