

CN4WUN

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	148039 KM
File nr. :	1438833	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GJE561 / VSSZZZ7NZEV513407 /		yr of constructionr :	/
E-File nr. :		First registration :	21/02/2014
VFS-nr. :		Color :	BLACK
Make + Model :	SEAT / ALHAMBRA	Fuel type :	DIESEL
Object nr. :	10121	Fuel :	
Classification :	I	Environment Class:	EURO 5
Customer company :	INFRA X LIMBURG	Co2:	146g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	7 [x]
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1968
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	140	kW:	103
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :		
First aid kit :		Warning triangle :	OK	[x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6/	Rim :	/
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	V
Rear tyre	225	50	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

Conclusion

Bodywork \& windows

[x] BONNET/CENTER/LEFT/FRONT CHIPS

[x] BONNET/CENTER/RIGHT/FRONT CHIPS

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

[x] FRONT DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE MEERDERE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

[x] REAR WINDOW/LEFT WINDOW DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
5 10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR

[x] REAR DOOR/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	382.02 EUR		50 %	382.02 EUR

[x] REAR DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
5	1	BACK WINDOW	300.00 EUR	50 %	300.00 EUR

1	2	3	4	5	6	7	8	9	10
254.16	382.02	254.16	115.56	348.00	0	0	0	0	0
127.08	191.01	127.08	115.56	174.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
115.56	1238.34	0	1353.90
HOG: 0	BG: 2		NA Deprec. 734.73
			0.00%
			TOTAL 734.73

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 19/09/2017 Hour : 13:04 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	