

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	163374 KM
File nr. :	1439403	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EZX097 / VF1JZNAA648960070 /		yr of constructionr :	/
E-File nr. :		First registration :	02/05/2013
VFS-nr. :		Color :	BLACK
Make + Model :	RENAULT / GRAND SCENIC	Fuel type :	DIESEL
Object nr. :	47067	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Atos Belgium NV	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	GR.SCENIC Energ.Privilege 5pl.FAP 130PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	MONOVOLUME	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	131	kW:	96
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	KLÉBER	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	1.6-2/	Rim :			/	Hubcap :
Wheel FR :	[x]	KLÉBER	Tyre :	[x]	OK	[x]	2-4/	Rim :		/	Hubcap :
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	1.6-2/	Rim :			/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	50	R	17	V
Rear tyre	215	50	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/RIGHT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] REAR DOOR/RIGHT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] FRONT BUMPER/CENTER/RIGHT CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] REAR THRESHOLD/LEFT/REAR SCRATCH WITH PAINT DAMAGE DEURINSLAG

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR	115.56 EUR

Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

1	2	3	4	5	6	7	8	9	10
115.56	95.00	0	0	0	0	0	0	0	0
115.56	95.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
210.56	0	0	210.56
HOG: 0	BG: 0		NA Deprec. 210.56
			0.00%
			TOTAL 210.56

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 20/09/2017 Hour : 11:10 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	