

www.vabfleetservices.be Date: 12/09/2017 1/5

CKCMNM

[X] EFFECTIVE [] NOT EXECUTED

[X] COLLECTION

[] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 114597 KM File nr. : Mileage start / arrival: 0 / 01436654 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1FMS094 / WVWZZZ3CZEE031490 / E-File nr. : First registration: 21/08/2013 Color: VFS-nr.: **GREY** Make + Model : Fuel type : VOLKSWAGEN / PASSAT **DIESEL** Object nr. : Fuel: Classification: **Environment Class:** EURO 5 Customer company: Co2: DELAWARE CONSULTING BVBA 114g/km Driver : Remote controls: 2 LEATHER Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type: PASSAT BER Comfortline BMT 105PK Country registration: **BELGIUM**

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		1	



Warning vest:

APPRAISAL

www.vabfleetservices.be Date: 12/09/2017 2/5

Original registr. number: OK Service manual: OK

Cert. of reg. / Part 1: Cert. of conformity: OK

Cert. of reg. copy / Part 2: OK Insurance certificate: [x]

Tax certificate : Navigation CD/SD/DVD

Fuel card: Car radio: OK

Mobile phone kit: Extinguisher: OK

Warning triangle : OK

Transport licence:

First aid kit: OK Oil level: OK

Jack, wheelspanner: Filled up: 0

Wheels and tyres: Summer tires

OK

Wheel FL:	[x]	UNIROYAL	Tyre:		OK	[x]	2-4 /	Rim:		WHEEL SCRATCHED	/	Hubcap:
Wheel RL:	[x]	UNIROYAL	Tyre:		OK		4-6 /	Rim:	[x]		/	Hubcap:
Wheel FR:	[x]	UNIROYAL	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/	Hubcap:
Wheel RR:	[x]	UNIROYAL	Tyre:		OK		4-6 /	Rim:			/	Hubcap:
Wheel RES:	[x]		Tyre:		OK		/	Rim:			/	Hubcan:

	Width	Height	Туре	Rim	Index
Front tyre	215	55	R	16	W
Rear tyre	215	55	R	16	W

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 12/09/2017 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

]	REAR MUDGUARD/LEFT/FRONT	DENT	
	REAR DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
	WINDSCREEN/CENTER/RIGHT	WINDOW DAMAGE	ZONDER BARST
	FRONT DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
	BONNET/CENTER/RIGHT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)	
	FRONT BUMPER/LEFT	SCRATCH WITH PAINT DAMAGE	ONDERKANT
	FRONT BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	ONDERKANT

OUTSIDE MIRROR SCRATCH WITH PAINT DAMAGE

Description

STATUS: NOT ACCEPTABLE

Number Code

REAR BUMPER/RIGHT/RIGHT		DENT	+ SIERLIJST	
	Repair paint - LI	New paint - E	Depr.	Total
1 5 LU =24.00 EUR	211.80 EUR		50 %	235.80 EUF
REAR MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE	+DEUKJE	
Number Code	Description	Unit price	Depr.	Total
2 I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

1	1	SIERLIJST					30.00 E	UR 50 %		30.00 EUR
	1	2	2	1	5	6	7	Q	۵	10

Unit price

Depr.

Total

1	2	3	4	5	6	7	8	9	10
265.80	115.56	0	0	0	0	0	0	0	0
132.90	115.56	0	0	0	0	0	0	0	0



www.vabfleetservices.be Date: 12/09/2017 4/5

INNOVATIVE	TRADITIONAL	GENERAL		
115.56	265.80	0		381.36
HOG: 0	BG: 0		NA Deprec.	248.46
			0.00%	
			TOTAL	248.46



12/09/2017 Date: www.vabfleetservices.be 5/5

[x] = Status Modification

Pictures: No					
CIRCUMS	FANCES		NORMAL CONCLU	JSION	
Extra Time :	0 min	Waiting time: 0 m Reason:	in	Towing time : Reason :	0 min
NOT EXECUTED : Reason :	No	I			
Remark :	REPSET OK				
Prices in EUR w	ithout VAT				
Authorized by customer:			Executed by VAB Fleet Se	ervices	
Remark authorized	customer :				
Date :	12/09/2017	Hour: 13:25			
Company :					
Executed by VAB FI Services	eet				
E-Mail :	@				
Signature authorized l	by customer				
,					