

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	156755 KM
<b>File nr. :</b>	1436648	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1DTP680 / VF30ARHE8CS080032 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	23/08/2012
<b>VFS-nr. :</b>		<b>Color :</b>	SILVER
<b>Make + Model :</b>	PEUGEOT / 5008	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	SOA PEOPLE SA	<b>Co2:</b>	140g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	5 [x]
<b>Vehicle type :</b>	5008 Allure FAP 150PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	MONOVOLUME	<b>Engine size:</b>	1997
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	150	<b>kW:</b>	110
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK	Insurance certificate :	
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	[x]	Oil level :	OK
		Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	0-1.6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x] 1.6-2/	Rim :		WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	[x]	BRIDGESTONE	Tyre :	OK	0-1.6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x] 0-1.6/	Rim :		WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]	ANDERE	Tyre :	OK	/	Rim :			/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	215	50	R	17	W
Rear tyre	215	50	R	17	W

Remark : REP. KIT OK

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/RIGHT/CENTER	DENT	
[x]	FRONT DOOR/RIGHT/FRONT	DENT	+POL.
[x]	BONNET/RIGHT	CHIPS	
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS	+POL.
[x]	FRONT/LEFT	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT BUMPER/LEFT	SCRATCH WITH PAINT DAMAGE	

### Interior

[x]	BOOT LID IN	SCRATCHED
[x]	BOOT IN L	SCRATCHED
[x]	BOOT IN R	SCRATCHED

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
				<b>Total</b>
3	0 LU =0.00 EUR	308.20 EUR		50 %
				308.20 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT		
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>
				<b>Depr.</b>
				<b>Total</b>
4	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR
				63.00 EUR
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	FLANKBESCHERMER	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
				<b>Total</b>
3	0 LU =0.00 EUR	0 EUR		50 %

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

## Interior

[x] LUGGAGE COVER MISSING/INCOMPLETE

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR	0 EUR		50 %	

## Others

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

## Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	SIDE PROTECTION PAINTED	100.00 EUR	50 %	100.00 EUR

Number	Code	Description	Unit price	Depr.	Total
5	1	LUGGAGE COVER	240.00 EUR	50 %	240.00 EUR

1	2	3	4	5	6	7	8	9	10
285.00	115.56	408.20	63.00	240.00	0	0	0	0	0
285.00	115.56	204.10	63.00	120.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
463.56	648.20	0	<b>1111.76</b>
HOG: 0	BG: 0		NA Deprec. 787.66
			0.00%
			<b>TOTAL 787.66</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b> NAVI OK ././ CONTROLE OVVBH = ZIE VORIG BESTEK [x]		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 15/09/2017 <b>Hour :</b> 10:17 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	