

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	102629 KM
File nr. :	1439402	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FBM286 / VF1JZ140648764625 /		yr of constructionr :	/
E-File nr. :		First registration :	16/05/2013
VFS-nr. :		Color :	GREY
Make + Model :	RENAULT / SCENIC	Fuel type :	DIESEL
Object nr. :	46483	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	RANDSTAD GROUP BELGIUM NV	Co2:	105g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	SCENIC Energ.Expression 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher :
First aid kit :	Warning triangle : OK [x]
Jack, wheelspanner : OK [x]	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap : [x] BROKEN / CRACKED
Wheel RL : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 2-4/ Rim : / Hubcap : [x] BROKEN / CRACKED
Wheel RR : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel RES: [x] MICHELIN Tyre : OK [x] >6/ Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	H
Rear tyre	205	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/REAR	DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	FRONT DOOR/RIGHT/REAR	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
6	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	BONNET/CENTER/LEFT/FRONT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
2	10 LU =48.00 EUR	290.08 EUR		50 %	338.08 EUR
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	ROOF/CENTER/LEFT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
7	30 LU =144.00 EUR	481.50 EUR		50 %	625.50 EUR

Interior

[x]	SEAT FR	STAIN				
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR
[x]	SEAT REAR L	STAIN				
	Number	Code	Description	Unit price	Depr.	Total
1	I 2	i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		29.16 EUR

Others

HUB CAP FL

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
43.74	338.08	211.80	211.80	60.00	318.35	625.50	0	0	0
43.74	169.04	105.90	105.90	30.00	159.18	312.75	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
43.74	1765.53	0	1809.27
HOG: 0	BG: 0		NA Deprec. 926.50
			0.00%
			TOTAL 926.50

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 19/09/2017 Hour : 11:04 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	