

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	159313 KM
File nr. :	1429009	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DVU407 / YV1MV8481D2009365 /		yr of constructionr :	/
E-File nr. :		First registration :	12/09/2012
VFS-nr. :		Color :	BLACK
Make + Model :	VOLVO / V40	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KBC BANK NV	Co2:	94g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	V40 D2 Base 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate : OK [x]
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RL : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RR : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RES: [x] ANDERE Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR DOOR/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR MUDGUARD/LEFT/CENTER	DENT	
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT	
[x]	REAR DOOR/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	ROOF STYLE/CENTER/LEFT	DENT	
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	BONNET/CENTER/RIGHT	DENT	MEERDERE
[x]	FRONT MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE	

Interior

[x]	FLOOR FL	SCRATCHED
[x]	SEAT FL	SCRATCHED

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	SCRATCH (WITHOUT PAINT DAMAGE)
-----	------------------------------	--------------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/CENTER	DENT				
	Number	Code	Description	Unit price	Depr.	Total
	3	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT THRESHOLD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E	Depr.	Total
	2	0 LU =0.00 EUR	310.50 EUR		50 %	310.50 EUR

[x]	FRONT THRESHOLD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	310.50 EUR		50 %	310.50 EUR
[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
5	I1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	310.50	63.00	310.50	95.00	0	0	0	0	0
105.90	155.25	63.00	155.25	95.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
158.00	832.80	0	990.80
HOG: 0	BG: 0		NA Deprec. 574.40
			0.00%
			TOTAL 574.40

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/09/2017 Hour : 09:50 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	