

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	92542 KM
File nr. :	1435535	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DNW117 / WVGZZZ1TZCW116784 /		yr of constructionr :	/
E-File nr. :		First registration :	03/07/2012
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / TOURAN	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	EDF LUMINUS	Co2:	140g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	TOURAN Highline 140PK	Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1968
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	140	kW:	103
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:	03/07/2019	Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK	Insurance certificate :	OK
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :	OK	Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	MICHELIN	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x] HANGKOOK	Tyre :	OK	4-6/	Rim :	/	Hubcap :
Wheel FR :	MICHELIN	Tyre :	[x] OK [x]	2-4/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :
Wheel RR :	[x] HANGKOOK	Tyre :	OK	4-6/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE	CHARGEMENT
[x]	REAR DOOR/CENTER/RIGHT	DENT	
[x]	REAR WINDOW/RIGHT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	REAR THRESHOLD/LEFT/REAR	DENT	IN
[x]	REAR DOOR/LEFT/CENTER	DENT	2X
[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	BOORD DEUR
[x]	REAR DOOR/RIGHT/CENTER	DENT	
[x]	REAR THRESHOLD/RIGHT/REAR	DENT	IN
[x]	REAR DOOR/RIGHT/FRONT	DENT	
[x]	FRONT MUDGUARD/RIGHT/REAR	DENT	
[x]	BONNET/CENTER/LEFT/FRONT	DENT	
[x]	FRONT BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	L/R ONDERKANT

Interior

[x]	BOOT LID IN	SCRATCHED
-----	-------------	-----------

STATUS: NOT ACCEPTABLE

Others

RIM REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR		50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	ALLOY WHEEL	211.20 EUR	50 %	211.20 EUR

1	2	3	4	5	6	7	8	9	10
211.20	0	0	0	0	0	0	0	0	0
105.60	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	211.20	0	211.20
HOG: 0	BG: 0		NA Deprec. 105.60
			0.00%
			TOTAL 105.60

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/09/2017 Hour : 16:27 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	