

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	111438 KM
File nr. :	1437266	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
QF8359 / WVWZZZ7NZFV001620 /		yr of constructionr :	/
E-File nr. :		First registration :	20/08/2014
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / SHARAN	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	FERRERO TRADING LUX	Co2:	g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :		Country registration :	LUXEMBOURG

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1968
Gear box :	Automaat algemeen	Number of places:	7
Number of gears:		Number of doors:	5
HP:	177	kW:	130
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	
Cert. of reg. / Part 1:		Cert. of conformity :	
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK [x]	>6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK [x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	UNIROYAL	Tyre :	[x] OK [x]	>6/	Rim :	[x] WHEEL SCRATCHED	Hubcap :	
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK [x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	V
Rear tyre	225	50	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] FRONT DOOR/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE) POLIEREN
- [x] FRONT MUDGUARD/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

	Repair paint - LI	New paint - E	Depr.	Total
[x] WINDSCREEN/CENTER/RIGHT HOLE/CRACK/TORN				
3 0 LU =0.00 EUR	0 EUR		50 %	
	Repair paint - LI	New paint - E	Depr.	Total
3 25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR
[x] FRONT BUMPER/CENTER/RIGHT DENT				
	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR	45.88 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	WIND SCREEN	440.64 EUR	50 %	440.64 EUR

1	2	3	4	5	6	7	8	9	10
45.88	95.00	560.64	254.16	0	0	0	0	0	0
45.88	95.00	280.32	127.08	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
140.88	814.80	0	955.68
HOG: 0	BG: 2		NA Deprec. 548.28
			0.00%
			TOTAL 548.28

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 21/09/2017 Hour : 08:23 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	