

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	66373 KM
<b>File nr. :</b>	1436697	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1KVY609 / JTDZS3EU503111799 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	17/07/2015
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	TOYOTA / GRAND PRIUS+	<b>Fuel type :</b>	HYBRID
<b>Object nr. :</b>	687955BE300002	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 6
<b>Customer company :</b>	TOYOTA MOTOR EUROPE	<b>Co2:</b>	96g/km
<b>Driver :</b>	DAWAGNE, MARC	<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	7 [x]
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	MONOVOLUME	<b>Engine size:</b>	1798
<b>Gear box :</b>	Automaat algemeen	<b>Number of places:</b>	7
<b>Number of gears:</b>		<b>Number of doors:</b>	5
<b>HP:</b>	99	<b>kW:</b>	73
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	OK	[x]	
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	NOK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK	[x]
Jack, wheelspanner :	OK	[x]	Oil level :		
			Filled up :	0	

## Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]		
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]	ANDERE	Tyre :	OK		/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	V
Rear tyre	205	60	R	16	V

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR DOOR/RIGHT/CORNER/BELOW	DENT	INSTAP
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT MUDGUARD/RIGHT/FRONT	CHIPS	

### Interior

[x]	DOOR IN REAR L	SCRATCHED
[x]	BOOT LID IN	SCRATCHED

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE	ZWARTE RAND	
		Repair paint - LI	New paint - E	
		Depr.	Total	
1	20 LU =96.00 EUR	0 EUR	50 %	96.00 EUR

### Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WIND SCREEN	440.64 EUR	50 %	440.64 EUR

1	2	3	4	5	6	7	8	9	10
536.64	0	0	0	0	0	0	0	0	0
268.32	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	536.64	0	<b>536.64</b>
HOG: 0	BG: 2		NA Deprec. 268.32
			0.00%
			<b>TOTAL 268.32</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 12/09/2017 <b>Hour :</b> 09:42 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b>	Executed by VAB Fleet Services
<b>Signature authorized by customer</b> 	