

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	79167 KM
File nr. :	1438566	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HLY904 / YV1MV8481F2189882 /		yr of constructionr :	/
E-File nr. :		First registration :	25/08/2014
VFS-nr. :		Color :	WHITE
Make + Model :	VOLVO / V40	Fuel type :	DIESEL
Object nr. :	76409	Fuel :	
Classification :	F	Environment Class:	EURO 5
Customer company :	AKKA BELGIUM	Co2:	88g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1: OK [x]	Cert. of conformity : OK
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RL : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 2-4/ Rim : / Hubcap :
Wheel RR : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE

Interior

[x]	DOOR IN REAR L	SCRATCHED
-----	----------------	-----------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	DENT				
			Repair paint - LI	New paint - E	Depr.	Total
4	15 LU =72.00 EUR		0 EUR	235.80 EUR	50 %	307.80 EUR
[x]	REAR MUDGUARD/LEFT/FRONT	DENT				
			Repair paint - LI	New paint - E	Depr.	Total
4	5 LU =24.00 EUR		308.20 EUR		50 %	332.20 EUR
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR		318.35 EUR		50 %	318.35 EUR
[x]	FRONT MUDGUARD/LEFT/FRONT	DENT				
			Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR		220.18 EUR		50 %	220.18 EUR
[x]	FRONT BUMPER/LEFT/CORNER	SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR		211.80 EUR		50 %	211.80 EUR

Interior

[x]	SEAT FL	STAIN				
	Number	Code	Description	Unit price	Depr.	Total
1	11	i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR

[x] SEAT REAR L STAIN

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-rein-07	CLEANING (PER 15')	14.58 EUR	14.58 EUR

Others

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
4	1	REAR BUMPER	343.20 EUR	50 %	343.20 EUR

1	2	3	4	5	6	7	8	9	10
29.16	431.98	318.35	983.20	95.00	0	0	0	0	0
29.16	215.99	159.18	491.60	95.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
124.16	1733.53	0	1857.69
HOG: 0	BG: 0		NA Deprec. 990.92
			0.00%
			TOTAL 990.92

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 18/09/2017 Hour : 15:03 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	