

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	207930 KM
File nr. :	1437816	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CHZ256 / VF38DRHDABL098572 /		yr of constructionr :	/
E-File nr. :		First registration :	01/12/2011
VFS-nr. :		Color :	BLACK
Make + Model :	PEUGEOT / 508	Fuel type :	DIESEL
Object nr. :	68036	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	MAJESTIC PRODUCTS BV	Co2:	149g/km
Driver :		Remote controls:	2
Covering :	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	508 BER Allure 136PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1997
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	4
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	OK [x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	FULDA	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	FULDA	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	FULDA	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	FULDA	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]	FULDA	Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	17	V
Rear tyre	215	55	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/LEFT/LEFT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x] REAR DOOR/CENTER/LEFT OTHER DAMAGES CHEMISCHE INWERKING

	Repair paint - LI	New paint - E	Depr.	Total
7 0 LU =0.00 EUR	301.68 EUR		50 %	301.68 EUR

[x] REAR MUDGUARD/LEFT/FRONT DENT

Number	Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x] REAR DOOR/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] REAR THRESHOLD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR	310.50 EUR		50 %	310.50 EUR

[x] FRONT DOOR/LEFT/FRONT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] FRONT DOOR/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] FRONT MUDGUARD/LEFT/REAR SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

[x] FRONT MUDGUARD/RIGHT/REAR

SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

1	2	3	4	5	6	7	8	9	10
211.80	538.53	538.53	318.35	63.00	310.50	301.68	0	0	0
105.90	269.26	269.26	159.18	63.00	155.25	150.84	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	2219.39	0	2282.39
HOG: 0	BG: 0		NA Deprec. 1172.70
			0.00%
			TOTAL 1172.70

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 15/09/2017 Hour : 13:53 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	