

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	161966 KM
File nr. :	1432942	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FAH604 / VF37J9HL0DJ628622 /		yr of constructionr :	/
E-File nr. :		First registration :	06/05/2013
VFS-nr. :		Color :	GREY
Make + Model :	PEUGEOT / PARTNER	Fuel type :	DIESEL
Object nr. :	36528	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Febelco CV	Co2:	134g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	0 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	PARTNER TEPEE OUTDOOR 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] BRIDGESTONE Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] BRIDGESTONE Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel FR : [x] BRIDGESTONE Tyre : [x] OK [x] 2-4/ Rim : / Hubcap :
Wheel RR : [x] BRIDGESTONE Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	H
Rear tyre	215	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE
- [x] REAR DOOR/LEFT/FRONT SCRATCH WITH PAINT DAMAGE
- [x] REAR DOOR/RIGHT/CENTER DENT
- [x] FRONT/LEFT DENT

Interior

- [x] DOOR IN FL SCRATCHED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] REAR DOOR/RIGHT/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	226.26 EUR		50 %	226.26 EUR

- [x] ROOF/CENTER/LEFT OTHER DAMAGES SL HERSTELD

Number	Code	Description	Unit price	Depr.	Total
0	0				

1	2	3	4	5	6	7	8	9	10
226.26	0	0	0	0	0	0	0	0	0
113.13	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	226.26	0	226.26
HOG: 0	BG: 3		NA Deprec. 113.13
			0.00%
			TOTAL 113.13

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 18/09/2017 Hour : 14:17 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	