

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	246358 KM
File nr. :	1439836	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ARE193 / WV1ZZZ7HZBH095393 /		yr of constructionr :	/
E-File nr. :		First registration :	08/03/2011
VFS-nr. :		Color :	WHITE
Make + Model :	VOLKSWAGEN / TRANSPORTER	Fuel type :	DIESEL
Object nr. :	9461	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KUMPEN NV	Co2:	190g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	TRANSP.1000 B/F SWB 102PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	BESTELWAGEN	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	4
HP:	102	kW:	75
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	T
Rear tyre	205	60	R	16	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/REAR	DENT	X2
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	BONNET/CENTER/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	
[x]	BONNET/CENTER/RIGHT/FRONT	DENT	
[x]	REAR DOOR/LEFT/LEFT	DENT	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	DENT					
		Repair paint - LI	New paint - E	Depr.	Total		
4	0 LU =0.00 EUR	0 EUR		50 %			
		Repair paint - LI	New paint - E	Depr.	Total		
4	15 LU =72.00 EUR	0 EUR		50 %	72.00 EUR		
[x]	ROOF/CENTER/RIGHT	DENT		MEERDERE			
		Repair paint - LI	New paint - E	Depr.	Total		
2	20 LU =96.00 EUR	361.13 EUR		50 %	457.13 EUR		
[x]	REAR DOOR/RIGHT/FRONT	DENT					
		Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-uitd-01		BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT THRESHOLD/RIGHT/REAR			SCRATCH WITH PAINT DAMAGE			
		Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-sp-01		SPOTREPAIR	115.56 EUR		115.56 EUR

Interior

[x]	BOOT LID IN	MISSING/INCOMPLETE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Accessories and others

[x] OUTSIDE MIRROR RIGHTHAND SIDE BROKEN / CRACKED

	Repair paint - LI	New paint - E	Depr.	Total
6 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	HENDEL	60.00 EUR	50 %	60.00 EUR
Number	Code	Description	Unit price	Depr.	Total
4	1	REAR BUMPER	257.40 EUR	50 %	257.40 EUR
Number	Code	Description	Unit price	Depr.	Total
6	1	MIRROR	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
84.00	457.13	63.00	329.40	115.56	114.00	0	0	0	0
42.00	228.56	63.00	164.70	115.56	57.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
178.56	984.53	0	1163.09
HOG: 0	BG: 3		NA Deprec. 670.82
			0.00%
			TOTAL 670.82

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 25/09/2017 Hour : 11:12 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	