

www.vabfleetservices.be Date: 22/09/2017 1/5

**CKXVOC** 

#### [X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 119734 KM File nr. : Mileage start / arrival: 0 / 01437132 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1FEM494 / WDD2122051A811172 / E-File nr. : First registration: 07/06/2013 Color: VFS-nr.: **GREY** Make + Model : Fuel type : MERCEDES / E BREAK **DIESEL** Object nr. : Fuel: Classification: **Environment Class:** EURO 5 Customer company: Co2: BELGACOM INS/FLEET NV 135g/km Driver : Remote controls: 2 TISSUE Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type: E BRE 200CDI BE Start/Stop 136PK Country registration: **BELGIUM** 

| VAT over the margin - car:   |            | Metallic paint:     | Yes     |
|------------------------------|------------|---------------------|---------|
| Variant car:                 | BREAK      | Engine size:        | 2143    |
| Gear box :                   | Manueel    | Number of places:   | 5       |
| Number of gears:             | 6          | Number of doors:    | 5       |
| HP:                          | 136        | kW:                 | 100     |
| Fisc HP                      |            | Imported vehicle:   |         |
| Animals transported:         |            | Smoked in vehicle:  | No      |
| Due date vehicle inspection: | 07/06/2018 | Extra set of tires: | No      |
|                              |            | Use:                | Unknown |
|                              |            |                     |         |
| General condition:           |            |                     |         |



www.vabfleetservices.be Date: 22/09/2017 2/5

| Original registr. number :   | OK |     | Service manual :        | OK | [x] |
|------------------------------|----|-----|-------------------------|----|-----|
| Cert. of reg. / Part 1:      | OK | [x] | Cert. of conformity:    | OK |     |
| Cert. of reg. copy / Part 2: |    | [x] | Insurance certificate : |    |     |
| Warning vest :               | OK | [x] | Transport licence :     |    | [x] |
| Tax certificate :            |    |     | Navigation CD/SD/DVD    |    |     |
| Fuel card :                  |    |     | Car radio :             | OK | [x] |
| Mobile phone kit :           |    |     | Extinguisher :          | OK | [x] |
|                              |    |     | Warning triangle :      | OK | [x] |
| First aid kit :              | OK | [x] | Oil level :             | OK | [x] |
| Jack, wheelspanner :         | OK | [x] | Filled up :             | 0  |     |

#### Wheels and tyres: Summer tires

|            |     | [x] Width   |       |     |    | He  | ight  |      |     | Type            |   | Rim       | Index |   |
|------------|-----|-------------|-------|-----|----|-----|-------|------|-----|-----------------|---|-----------|-------|---|
| Wheel RES: | [x] | CONTINENTAL | Tyre: |     | OK | [x] | 2-4 / | Rim: |     |                 |   | / Hubcap: |       |   |
| Wheel RR:  | [x] | MICHELIN    | Tyre: |     | OK | [x] | 2-4 / | Rim: | [x] | WHEEL SCRATCHED | ) | / Hubcap: |       |   |
| Wheel FR:  | [x] | MICHELIN    | Tyre: | [x] | OK | [x] | 2-4 / | Rim: | [x] | WHEEL SCRATCHED | ) | / Hubcap: |       |   |
| Wheel RL:  | [x] | MICHELIN    | Tyre: |     | OK | [x] | 2-4 / | Rim: |     |                 |   | / Hubcap: |       |   |
| Wheel FL:  | [x] | MICHELIN    | Tyre: |     | OK | [x] | 2-4 / | Rim: | [x] | WHEEL SCRATCHED | ) | / Hubcap: |       | П |

| <br>[x]    | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225   | 55     | R    | 16  | W     |
| Rear tyre  | 225   | 55     | R    | 16  | W     |

Remark:

#### Wheels and tyres:

| Wheel FL:  | Tyre: | OK | / | Rim: | / Hubcap: |
|------------|-------|----|---|------|-----------|
| Wheel RL:  | Tyre: | OK | / | Rim: | / Hubcap: |
| Wheel FR:  | Tyre: | OK | / | Rim: | / Hubcap: |
| Wheel RR:  | Tyre: | OK | / | Rim: | / Hubcap: |
| Wheel RES: | Tyre: | OK | / | Rim: | / Hubcap: |
|            |       |    |   |      |           |

| _ | [x]        | Width | Height | Туре | Rim | Index |
|---|------------|-------|--------|------|-----|-------|
|   | Front tyre | 0     | 0      | R    | 0   |       |
|   | Rear tyre  | 0     | 0      | R    | 0   |       |

Remark:



www.vabfleetservices.be Date: 22/09/2017 3/5

#### STATUS: ACCEPTABLE / USAGE DAMAGE

| Boo  | dywork \& windows            |                                |            |
|------|------------------------------|--------------------------------|------------|
| [x]  | REAR BUMPER/CENTER/RIGHT     | SCRATCH WITH PAINT DAMAGE      | SOUS LAQUE |
| [x]  | REAR MUDGUARD/LEFT/FRONT     | SCRATCH WITH PAINT DAMAGE      | POLIR      |
| [x]  | REAR BUMPER/SIDE/RIGHT/FRONT | SCRATCH (WITHOUT PAINT DAMAGE) |            |
| [x]  | REAR MUDGUARD/RIGHT/FRONT    | DENT                           |            |
| [x]  | REAR DOOR/LEFT/CENTER        | DENT                           | 2X         |
| [x]  | REAR DOOR/RIGHT/CENTER       | DENT                           |            |
| [x]  | FRONT DOOR/LEFT/REAR         | DENT                           |            |
| [x]  | FRONT DOOR/LEFT/CENTER       | DENT                           |            |
| [x]  | FRONT DOOR/RIGHT/REAR        | DENT                           |            |
| [x]  | FRONT DOOR/RIGHT/CENTER      | CHIPS                          | POIGNEE    |
| [x]  | FRONT MUDGUARD/LEFT/FRONT    | SCRATCH WITH PAINT DAMAGE      |            |
| [x]  | BONNET/CENTER/LEFT/FRONT     | CHIPS                          |            |
| [x]  | FRONT BUMPER/CENTER/LEFT     | DENT                           |            |
| [x]  | FRONT BUMPER/RIGHT/CORNER    | SCRATCH WITH PAINT DAMAGE      | POLIR      |
| Inte | erior                        |                                |            |
| [x]  | BOOT LID IN                  | SCRATCHED                      |            |
| Acc  | cessories and others         |                                |            |
| [x]  | OUTSIDE MIRROR LEFTHAND SIDE | SCRATCH WITH PAINT DAMAGE      |            |

|     | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-----|---|---|---|---|---|---|---|---|---|----|
|     | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |
| - 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |



www.vabfleetservices.be Date: 22/09/2017 4/5

|   |            | GENERAL | TRADITIONAL | INNOVATIVE |
|---|------------|---------|-------------|------------|
| 0 |            | 0       | 0           | 0          |
| 0 | NA Deprec. |         | BG: 2       | HOG: 0     |
|   | 0.00%      |         |             |            |
| 0 | TOTAL      |         |             |            |



www.vabfleetservices.be Date: 22/09/2017 5/5

[x] = Status Modification

Pictures: No

| rictures: No               | •           |                            |                   |                    |                        |       |  |
|----------------------------|-------------|----------------------------|-------------------|--------------------|------------------------|-------|--|
| CIRCUMSTANCES              |             |                            | NORMAL CONCLUSION |                    |                        |       |  |
| Extra Time :               | 0 min       | Waiting time :<br>Reason : | 0 min             |                    | Towing time : Reason : | 0 min |  |
| NOT EXECUTED :<br>Reason : | No          | <b>I</b>                   |                   |                    |                        |       |  |
| Remark :                   | 1           |                            |                   |                    |                        |       |  |
| Prices in EUR w            | vithout VAT |                            |                   |                    |                        |       |  |
| Authorized by customer :   |             |                            | Exe               | cuted by VAB Fleet | t Services             |       |  |
| Remark authorized          | customer :  |                            |                   |                    |                        |       |  |
| Date :<br>Company :        | 22/09/2017  | <b>Hour:</b> 13:39         | ,                 |                    |                        |       |  |
| Executed by VAB F          | leet        |                            |                   |                    |                        |       |  |
| E-Mail :                   | @           |                            |                   |                    |                        |       |  |
| Signature authorized       | by customer |                            |                   |                    |                        |       |  |
|                            |             |                            |                   |                    |                        |       |  |