

www.vabfleetservices.be Date: 20/09/2017 1/5

CN7DLZ

### [X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	56892
File nr. :	1438884	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FPE168 / YV1MV8481E2097	7828 /	yr of constructionr :	/
E-File nr. :		First registration :	12/09/2013
VFS-nr. :		Color :	GREY
Make + Model :	VOLVO / V40	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification:		Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	88g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	V40 D2 Base 115PK	Country registration :	BELGIUM

Variant car:		Engine size:	1560			
Gear box :	Manueel	Number of places:	5			
Number of gears:	6	Number of doors:	5			
HP:	114	kW:	84			
Fisc HP		Imported vehicle:				
Animals transported:		Smoked in vehicle:				
Due date vehicle inspection:		Extra set of tires:				
		Use:	Unknown			
General condition:						

Metallic paint:

Yes



20/09/2017 www.vabfleetservices.be Date: 2/5

Original registr. number : OK OK Service manual:

Cert. of reg. / Part 1: OK Cert. of conformity: OK

Insurance certificate: Cert. of reg. copy / Part 2: [x]

Warning vest: Transport licence: Tax certificate: Navigation CD/SD/DVD

Fuel card : Car radio: OK

Mobile phone kit : Extinguisher: OK

> Warning triangle: OK

Oil level: OK First aid kit : OK [x]

Filled up : 0 Jack, wheelspanner : [x]

#### Wheels and tyres: Summer tires

Wheel FL:	MICHELIN	Tyre:	OK	2-4 /	Rım :	WHEEL SCRATCHED	/	Hubcap :
Wheel RL:	MICHELIN	Tyre:	OK	4-6 /	Rim:		/	Hubcap:
Wheel FR:	MICHELIN	Tyre:	OK	2-4 /	Rim:	WHEEL SCRATCHED	/	Hubcap:
Wheel RR:	MICHELIN	Tyre:	OK	4-6 /	Rim:	WHEEL SCRATCHED	/	Hubcap:

Wheel RES: Tyre: OK Rim: / Hubcap:

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	Н
Rear tyre	205	55	R	16	Н

Remark:

#### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/	Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/	Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/	Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/	Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/	Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



Interior

## **APPRAISAL**

www.vabfleetservices.be Date: 20/09/2017 3/5

### STATUS: ACCEPTABLE / USAGE DAMAGE

Boo	Bodywork \& windows									
[x]	REAR MUDGUARD/RIGHT/CENTER	DENT								
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT								
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE								
[x]	REAR DOOR/RIGHT/CENTER	DENT	2X							
[x]	REAR THRESHOLD/RIGHT/REAR	DENT	BINNEN							
[x]	FRONT THRESHOLD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	BINNEN							
[x]	FRONT MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE								
[x]	BONNET/CENTER/LEFT	DENT								
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS								
	FRONT/RIGHT	SCRATCH WITH PAINT DAMAGE								
[x]	FRONT BUMPER/LEFT	SCRATCH WITH PAINT DAMAGE								
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE								
Inte	rior									
[x]	SEAT FR	STAIN								
[x]	SEAT REAR L	STAIN								
STA	STATUS: NOT ACCEPTABLE									

[x]	SEAT FL			BURNT			
	Number Code Description			Unit price	Depr.	Total	
1	<b>1</b> I1	i-vab-intvnl-01	VINYL REPAIR		82.20 EUR		82.20 EUR

l	1	2	3	4	5	6	7	8	9	10
	82.20	0	0	0	0	0	0	0	0	0
	82.20	0	0	0	0	0	0	0	0	0



www.vabfleetservices.be Date: 20/09/2017 4/5

		GENERAL	TRADITIONAL	INNOVATIVE
82.20		0	0	82.20
82.20	NA Deprec.		BG: 0	HOG: 0
	0.00%			
82.20	TOTAL			



www.vabfleetservices.be Date: 20/09/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMST	TANCES		NORMAL C	CONCLUSION	
Extra Time :	0 min	Waiting time: 0 m	in	Towing time :	0 min
		Reason :		Reason:	
NOT EXECUTED:	No	•		•	
Reason:					
Remark:					
Prices in EUR wi	thout VAT				
Authorized by customer :			Executed by VAB	Fleet Services	
Remark authorized co	ustomer :				
Date :	20/09/2017	<b>Hour:</b> 12:22			
Company:					
Executed by VAB Fle Services	eet				
E-Mail :	@				
Signature authorized by	y customer				