

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	90469 KM
File nr. :	1441788	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1NKV222 / YV1DZARC1G2908397 /		yr of constructionr :	/
E-File nr. :		First registration :	14/03/2016
VFS-nr. :		Color :	BROWN
Make + Model :	VOLVO / XC60	Fuel type :	
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	EURO 6
Customer company :	ONBEKEND	Co2:	117g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	1969
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	150	kW:	110
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK [x]	Warning triangle :	OK	[x]
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	1.6-2/	Rim :	/	Hubcap :	
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	1.6-2/	Rim :	/	Hubcap :
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	235	65	R	17	V
Rear tyre	235	65	R	17	V

Remark : REPSET OK

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE
- [x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE
- [x] REAR DOOR/RIGHT/REAR WINDOW DAMAGE

Interior

- [x] CENTER CONSOLE HOLE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

		Repair paint - LI	New paint - E	Depr.	Total
[x]	REAR DOOR/CENTER/LEFT		OTHER DAMAGES		
1	10 LU =48.00 EUR	301.68 EUR		50 %	349.68 EUR
[x]	FRONT DOOR/LEFT/FRONT		DENT	LAKSCHADE	
2	5 LU =24.00 EUR	318.35 EUR		50 %	342.35 EUR
[x]	FRONT/RIGHT		OTHER DAMAGES		
1	0 LU =0.00 EUR	0 EUR		50 %	
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 1	personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR	11.47 EUR

CLEANLINESS EXTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 1	mono-jeep-kl.bestelw-a-vab-reex-04	CLEANING EXTERIOR	13.20 EUR	13.20 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	GRILL	65.00 EUR	50 %	65.00 EUR

1	2	3	4	5	6	7	8	9	10
463.35	342.35	0	0	0	0	0	0	0	0
244.01	171.18	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
24.67	781.03	0	805.70
HOG: 0	BG: 0		NA Deprec. 415.18
			0.00%
			TOTAL 415.18

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 22/09/2017 Hour : 10:09 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	