

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	158321 KM
File nr. :	1440669	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EPO865 / WAUZZZ4G9DN098248 /		yr of constructionr :	/
E-File nr. :		First registration :	15/02/2013
VFS-nr. :		Color :	BROWN
Make + Model :	AUDI / A6	Fuel type :	DIESEL
Object nr. :	12466	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	NESTLE BELGILUX NV	Co2:	132g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	A6 AVANT 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	BREAK	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x] WHEEL SCRATCHED / Hubcap : [x]
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6/	Rim :	[x] WHEEL SCRATCHED / Hubcap : [x]	
Wheel RES:	[x]		Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	60	R	16	Y
Rear tyre	225	60	R	16	Y

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] REAR DOOR/LEFT/Front DENT
- [x] REAR DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE
- [x] BONNET/CENTER/RIGHT/Front CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

		Repair paint - LI	New paint - E	Depr.	Total
2	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4 personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR		45.88 EUR

1	2	3	4	5	6	7	8	9	10
45.88	139.56	0	0	0	0	0	0	0	0
45.88	127.56	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
161.44	24.00	0		185.44
HOG: 0	BG: 2		NA Deprec.	173.44
			0.00%	
			TOTAL	173.44

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 25/09/2017 Hour : 09:13 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	