

www.vabfleetservices.be Date: 25/09/2017 1/4

CO8LMY

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 120572 KM File nr. : Mileage start / arrival: 0 / 01439666 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1DUR341 / WAUZZZ8KXDA107609 / E-File nr. : First registration: 03/09/2012 Color: VFS-nr.: **BLUE D** Make + Model : Fuel type : AUDI / A4 **DIESEL** Object nr. : Fuel: 48506 Classification: **Environment Class:** EURO 5 Customer company: Co2: TMVW CVBA 117g/km Driver : Remote controls: 2 LEATHER Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type: A4 BER TDi 120PK Country registration: **BELGIUM**

VAT over the margin - car:	No	Metallic paint:	Yes				
Variant car:	BERLINE	Engine size:	1968				
Gear box :	Manueel	Number of places:	5				
Number of gears:	6	Number of doors:	4				
HP:	120	kW:	88				
Fisc HP		Imported vehicle:					
Animals transported:	No	Smoked in vehicle:	No				
Due date vehicle inspection:		Extra set of tires:	No				
		Use:	Unknown				
General condition:							



www.vabfleetservices.be Date: 25/09/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest:	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

		[x]	Width			He	ight			Туре		Rim	Index
Wheel RES:	[x]		Tyre:		OK		/	Rim:				/ Hubcap:	
Wheel RR:	[x]	SEMPERIT	Tyre:		OK	[x]	2-4 /	Rim:				/ Hubcap:	
Wheel FR:	[x]	SEMPERIT	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel RL:	[x]	SEMPERIT	Tyre:		OK	[x]	2-4 /	Rim:				/ Hubcap:	
Wheel FL:	[x]	SEMPERIT	Tyre :		OK	[x]	2-4 /	Rim:				/ Hubcap:	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	V
Rear tyre	225	50	R	17	V

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 25/09/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Во	dywork \& windows	
[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	ROOF STYLE/FRONT/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE
[x]	FRONT BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[X] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

	1	2	3	4	5	6	7	8	9	10
	211.80	0	0	0	0	0	0	0	0	0
ĺ	105.90	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	211.80	0		211.80
HOG: 0	BG: 0		NA Deprec.	105.90
			0.00%	
			TOTAL	105.90



www.vabfleetservices.be Date: 25/09/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES					
CIRCOMB	THICES		NORMAL CONCLU	JSION	
Extra Time :	0 min	Waiting time: 0 m Reason:	in	Towing time : Reason :	0 min
NOT EXECUTED : Reason :	: No	I		<u> </u>	
Remark :					
Prices in EUR v	without VAT				
Authorized by customer :			Executed by VAB Fleet So	ervices	
Remark authorized	customer :				
Date : Company :	25/09/2017	Hour: 10:23			
Executed by VAB F Services	leet				
E-Mail :	@				
Signature authorized	by customer				