

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: DIRTY [x]
<b>Owner :</b>		<b>Mileage :</b>	119973 KM
<b>File nr. :</b>	1437277	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
PR8324 / WAUZZZ8RXEA044042 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	18/10/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BROWN
<b>Make + Model :</b>	AUDI / Q5	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	
<b>Customer company :</b>	FERRERO TRADING LUX	<b>Co2:</b>	g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	SUV	<b>Engine size:</b>	1968
<b>Gear box :</b>	Automaat algemeen	<b>Number of places:</b>	5
<b>Number of gears:</b>		<b>Number of doors:</b>	5
<b>HP:</b>	177	<b>kW:</b>	130
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown
<b>General condition:</b>			

<b>Original registr. number :</b>		<b>Service manual :</b>	
<b>Cert. of reg. / Part 1:</b>		<b>Cert. of conformity :</b>	
<b>Cert. of reg. copy / Part 2:</b>		<b>Insurance certificate :</b>	
<b>Warning vest :</b>	OK [x]	<b>Transport licence :</b>	
<b>Tax certificate :</b>		<b>Navigation CD/SD/DVD</b>	OK [x]
<b>Fuel card :</b>		<b>Car radio :</b>	OK [x]
<b>Mobile phone kit :</b>		<b>Extinguisher :</b>	OK [x]
<b>First aid kit :</b>	OK [x]	<b>Warning triangle :</b>	OK [x]
<b>Jack, wheelspanner :</b>	OK [x]	<b>Oil level :</b>	OK [x]
		<b>Filled up :</b>	0

## Wheels and tyres: Summer tires

<b>Wheel FL:</b>	[x]	MICHELIN	<b>Tyre :</b>	OK [x]	2-4/	<b>Rim :</b>	[x]	WHEEL SCRATCHED	/	<b>Hubcap :</b>		
<b>Wheel RL :</b>	[x]	MICHELIN	<b>Tyre :</b>	OK [x]	2-4/	<b>Rim :</b>			/	<b>Hubcap :</b>		
<b>Wheel FR :</b>	[x]	MICHELIN	<b>Tyre :</b>	[x]	OK [x]	2-4/	<b>Rim :</b>	[x]	WHEEL SCRATCHED	/	<b>Hubcap :</b>	
<b>Wheel RR :</b>	[x]	MICHELIN	<b>Tyre :</b>	OK [x]	2-4/	<b>Rim :</b>			/	<b>Hubcap :</b>		
<b>Wheel RES:</b>	[x]		<b>Tyre :</b>	OK	/	<b>Rim :</b>			/	<b>Hubcap :</b>		

  

[x]	Width	Height	Type	Rim	Index
<b>Front tyre</b>	235	65	R	17	H
<b>Rear tyre</b>	235	65	R	17	H

**Remark :**

## Wheels and tyres:

<b>Wheel FL:</b>		<b>Tyre :</b>	OK	/	<b>Rim :</b>		/	<b>Hubcap :</b>	
<b>Wheel RL :</b>		<b>Tyre :</b>	OK	/	<b>Rim :</b>		/	<b>Hubcap :</b>	
<b>Wheel FR :</b>		<b>Tyre :</b>	OK	/	<b>Rim :</b>		/	<b>Hubcap :</b>	
<b>Wheel RR :</b>		<b>Tyre :</b>	OK	/	<b>Rim :</b>		/	<b>Hubcap :</b>	
<b>Wheel RES:</b>		<b>Tyre :</b>	OK	/	<b>Rim :</b>		/	<b>Hubcap :</b>	

  

[x]	Width	Height	Type	Rim	Index
<b>Front tyre</b>	0	0	R	0	
<b>Rear tyre</b>	0	0	R	0	

**Remark :**

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	THRESHOLD FRONT/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	IN
[x]	FRONT THRESHOLD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	IN
[x]	FRONT MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR
[x]	FRONT BUMPER/LEFT	SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
1	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

1	2	3	4	5	6	7	8	9	10
254.16	254.16	0	0	0	0	0	0	0	0
127.08	127.08	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	508.32	0	<b>508.32</b>
HOG: 0	BG: 2		NA Deprec. 254.16
			0.00%
			<b>TOTAL 254.16</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b> DOCUMENTEN WORDEN NAGESTUURD [x]		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 21/09/2017 <b>Hour :</b> 15:06 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	