

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	138919 KM
File nr. :	1441172	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FJD978 / WF0DXXGAKDDR76794 /		yr of constructionr :	/
E-File nr. :		First registration :	15/07/2013
VFS-nr. :		Color :	WHITE
Make + Model :	FORD / FIESTA	Fuel type :	DIESEL
Object nr. :	41806	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	PROMATIC-B NV	Co2:	87g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	FIESTA BER Trend ECONetic S/S 95PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	95	kW:	70
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	SEMPERIT	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :		
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :		
Wheel FR :	[x]	SEMPERIT	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :		
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	175	65	R	14	H
Rear tyre	175	65	R	14	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/LEFT CHIPS
- [x] ROOF/CENTER/RIGHT DENT
- [x] FRONT DOOR/LEFT/REAR SCRATCH (WITHOUT PAINT DAMAGE)
- [x] FRONT DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE
- [x] FRONT BUMPER/CENTER/LEFT CHIPS

Accessories and others

- [x] OUTSIDE MIRROR RIGHTHAND SIDE SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] REAR DOOR/RIGHT/FRONT DENT

Number	Code	Description	Unit price	Depr.	Total
2	I1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

1	2	3	4	5	6	7	8	9	10
0	63.00	0	0	0	0	0	0	0	0
0	63.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	0	0	63.00
HOG: 0	BG: 1		NA Deprec. 63.00
			0.00%
			TOTAL 63.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/09/2017 Hour : 09:02 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	