

CKH721

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	84955 KM
File nr. :	1436760	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FGX703 / WF0EXXGBBEDB33511 /		yr of constructionr :	/
E-File nr. :		First registration :	26/06/2013
VFS-nr. :		Color :	SILVER
Make + Model :	FORD / MONDEO	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	112g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	MONDEO BER EConetic Trend Style 115PK	Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:	26/06/2019	Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]	
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:		Insurance certificate :			
Warning vest :		Transport licence :			
Tax certificate :		Navigation CD/SD/DVD			
Fuel card :		Car radio :	OK	[x]	
Mobile phone kit :		Extinguisher :	OK	[x]	
First aid kit :	NOK	[x]	Warning triangle :	OK	[x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK	[x]
			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	KLÉBER	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	KLÉBER	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED
Wheel FR :	[x]	KLÉBER	Tyre :	[x]	OK	[x]	2-4/	Rim :	/
Wheel RR :	[x]	KLÉBER	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	W
Rear tyre	215	55	R	16	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	OTHER DAMAGES	DEPOT A POLIR RESINE
[x]	REAR MUDGUARD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	REAR BUMPER/SIDE/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE	POLIR
[x]	REAR DOOR/LEFT/REAR	OTHER DAMAGES	DEPOT A POLIR RESINE
[x]	REAR DOOR/LEFT/CENTER	DENT	
[x]	ROOF/REAR/LEFT	SCRATCH WITH PAINT DAMAGE	POLIR
[x]	FRONT DOOR/LEFT/CENTER	OTHER DAMAGES	DEPOT A POLIR RESINE
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	BORD PORTE
[x]	FRONT MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	POLIR+DEPOT A POLIR RESINE
[x]	BONNET/CENTER/RIGHT	OTHER DAMAGES	ISOLATION CAPOT DECHIREE
[x]	BONNET/CENTER/LEFT/FRONT	OTHER DAMAGES	G/D DEPOT A POLIR RESINE
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS	G/D
[x]	FRONT/LEFT	OTHER DAMAGES	A FIXER
[x]	FRONT BUMPER/LEFT	CHIPS	
[x]	FRONT BUMPER/CENTER/LEFT	DENT	
[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH WITH PAINT DAMAGE	
[x]	ROOF/CENTER/LEFT	OTHER DAMAGES	DEPOT A POLIR

Interior

[x]	CENTER CONSOLE	OTHER DAMAGES
[x]	DOOR IN REAR L	SCRATCHED
[x]	DOOR IN REAR RIGHT	SCRATCHED

[x] BOOT LID IN SCRATCHED

Accessories and others

[x] OUTSIDE MIRROR RIGHTHAND SIDE CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/RIGHT/RIGHT SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
6	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

[x] REAR DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
2	0 LU =0.00 EUR	Repair paint - LI	318.35 EUR	50 %	318.35 EUR
		New paint - E			

[x] REAR DOOR/RIGHT/FRONT DENT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x] WINDSCREEN/CENTER/RIGHT WINDOW DAMAGE

Number	Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR

[x] FRONT DOOR/RIGHT/CENTER DENT 4X

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x] FRONT THRESHOLD/RIGHT/CENTER OTHER DAMAGES JOINT INT BAS CAISSE

Number	Code	Description	Unit price	Depr.	Total
1	0 LU =0.00 EUR	Repair paint - LI	0 EUR	50 %	
		New paint - E			
1	5 LU =24.00 EUR	Repair paint - LI	0 EUR	50 %	24.00 EUR
		New paint - E			

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	JOINT INTERIEUR BAS CAISSE	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
54.00	318.35	63.00	63.00	58.80	115.56	0	0	0	0
27.00	159.18	63.00	63.00	58.80	115.56	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
300.36	372.35	0	672.71
HOG: 0	BG: 0		NA Deprec. 486.54
			0.00%
			TOTAL 486.54

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 22/09/2017 Hour : 15:13 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	