

www.vabfleetservices.be Date: 26/09/2017 1/5

CQE77X

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar: **KBC REMARKETING** Cleanliness: INT: DIRTY [x] EXT: DIRTY [x]

Color:

Owner: Mileage : 174115 KM

File nr. : Mileage start / arrival: 0 / 01441320

Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr : 1FHM015 / WF0AXXWPMADB66937 /

E-File nr. : First registration:

01/07/2013 VFS-nr.:

GREY Make + Model : Fuel type: FORD / KUGA **DIESEL**

Object nr. : Fuel: 77134

Environment Class: Classification: EURO 5

Customer company: Co2: ALSTOM BELGIUM SA 154g/km (4700001191)

Driver: Remote controls: 2

Covering: **TISSUE** Number keys : 2[x]

Vehicle kind: VEHICLE Seats (minivan):

Vehicle type: KUGA 4WD Trend 136PK Country registration: **BELGIUM**

VAT over the margin - car: No Metallic paint:

Variant car: Engine size: 1997

Gear box: Manueel Number of places: 5 Number of gears: 6 Number of doors: 5

HP: kW: 136 100

Fisc HP Imported vehicle:

Animals transported: Smoked in vehicle:

Extra set of tires: Due date vehicle inspection:

Use: Unknown

General condition:



www.vabfleetservices.be Date: 26/09/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest:	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :		
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	SEMPI	ERIT Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel RL:	[x]	SEMPI	ERIT Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel FR:	[x]	SEMPI	ERIT Tyre:	[x]	OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel RR:	[x]	SEMPI	ERIT Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel RES:	[x]		Tyre:		OK		/	Rim:		/	Hubcap:	
		[x]	Width			Не	eight	j	Туре		Rim	Index
Fron	t tyre		235				55		R		17	W
Rear	tyre		235				55		R		17	W

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 26/09/2017 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

Bod	ywork \& windows	
[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT MUDGUARD/LEFT/REAR	DENT
[x]	BONNET/CENTER/LEFT/FRONT	DENT
[x]	FRONT BUMPER/CENTER/LEFT	CHIPS
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	ROOF/CENTER/LEFT	DENT
STA	ATUS: NOT ACCEPTABLE	

Interior				
[x] BOOT LID IN		CARVED		
	Repair paint - LI	New paint - E	Depr.	Total
1 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
Others				

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	Ι3	personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR		34.41 EUR

Pieces					
Number	Code	Description	Unit price	Depr.	Total
1 1	UPHOLSTERY DOOR		90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
148.41	0	0	0	0	0	0	0	0	0
91.41	0	0	0	0	0	0	0	0	0



www.vabfleetservices.be Date: 26/09/2017 4/5

		GENERAL	TRADITIONAL	INNOVATIVE
148.41		0	114.00	34.41
91.41	NA Deprec.		BG: 0	HOG: 0
	0.00%			
91.41	TOTAL			



www.vabfleetservices.be Date: 26/09/2017 5/5

[x] = Status Modification

							Pictures: No
		SION	NORMAL CONCLU			ANCES	CIRCUMST
	0 min	Towing time : Reason :			Waiting Reason	0 min	Extra Time :
						No	NOT EXECUTED : Reason :
							Remark :
						thout VAT	Prices in EUR wit
			E . II WADEL . G				
		vices	Executed by VAB Fleet Ser				Authorized by customer :
						nstomer :	Remark authorized cu
				10:00	Hour :	26/09/2017	Date :
							Company:
						et	Executed by VAB Flee Services
						@	E-Mail :
						customer	Signature authorized by
				<u>-</u>			-
_				-		v customer	Signature authorized by