

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	63569 KM
File nr. :	1439743	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
933AXR / WF0XXXTTFX9G54100 /		yr of constructionr :	/
E-File nr. :		First registration :	18/09/2009
VFS-nr. :		Color :	WHITE
Make + Model :	FORD / TRANSIT	Fuel type :	DIESEL
Object nr. :	46260	Fuel :	
Classification :		Environment Class:	EURO 4
Customer company :	CMI MAINTENANCE & INGENIERIE SA	Co2:	221g/km
Driver :		Remote controls:	1
Covering :	IMITATION LEATHER	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	TRANSIT B/F 300M MWB Ambiente 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	No
Variant car:	BESTELWAGEN	Engine size:	2198
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	195	70	R	15	R
Rear tyre	195	70	R	15	R

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/CENTER	OTHER DAMAGES	ROEST
[x]	THRESHOLD FRONT/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	ROOF STYLE/FRONT/LEFT/CENTER	OTHER DAMAGES	
[x]	FRONT THRESHOLD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS	

Interior

[x]	SEAT FL	CARVED
-----	---------	--------

Accessories and others

[x]	VEH COVERED WITH STICKERS	STICKER(S)
-----	---------------------------	------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARDL/CENTER/RIGHT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	193.71 EUR		50 %	193.71 EUR
[x]	REAR DOOR/RIGHT/RIGHT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	226.26 EUR		50 %	226.26 EUR
[x]	REAR MUDGUARD/LEFT/CENTER	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR
[x]	REAR MUDGUARD/RIGHT/REAR	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR
[x]	FRONT MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR	165.13 EUR		50 %	165.13 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		58.32 EUR

1	2	3	4	5	6	7	8	9	10
289.47	226.26	231.15	193.71	165.13	0	0	0	0	0
173.90	113.13	115.58	96.86	82.56	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
58.32	1047.40	0	1105.72
HOG: 0	BG: 3		NA Deprec. 582.02
			0.00%
			TOTAL 582.02

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 27/09/2017 Hour : 13:56 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	