

Cleanliness:

Number keys:

Seats (minivan):

Country registration:

2[x]

BELGIUM

0

www.vabfleetservices.be Date: 22/09/2017 1/5

CIWQKG

INT: CLEAN [x] EXT: CLEAN [x]

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

KBC REMARKETING

TISSUE

FOCUS CLIP. ECOnetic Trend 88g 105PK

[x] = Status Modification

Commissionar:

Covering:

Vehicle kind:

Vehicle type:

General condition:

Owner: Mileage : 109387 KM File nr. : Mileage start / arrival: 0 / 01435518 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1EZF319 / WF0LXXGCBLDP31459 / E-File nr. : First registration: 26/04/2013 Color: VFS-nr.: **BLUE D** Make + Model : Fuel type : FORD / FOCUS **DIESEL** Object nr. : Fuel: Classification: **Environment Class:** EURO 5 Customer company: Co2: BELGACOM INS/FLEET NV 88g/kmDriver : Remote controls:

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
нр:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown



www.vabfleetservices.be Date: 22/09/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Winter tires

Wheel FL:	[x]	VREDESTEIN	Tyre:		OK	[x]	4-6/	Rim:	/	Hubcap:	
Wheel RL:	[x]	VREDESTEIN	Tyre:		OK	[x]	>6 /	Rim:	/	Hubcap:	[x] SCRATCHED
Wheel FR:	[x]	VREDESTEIN	Tyre:	[x]	OK	[x]	4-6/	Rim:	/	Hubcap:	[x] SCRATCHED
Wheel RR:	[x]	VREDESTEIN	Tyre:		OK	[x]	>6/	Rim:	/	Hubcap:	[x] SCRATCHED
Wheel RES:	[x]	HANGKOOK	Tyre:		OK	[x]	2-4 /	Rim:	/	Hubcap:	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	WINTER H
Rear tyre	205	55	R	16	WINTER H

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 22/09/2017 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

Boo	Bodywork \& windows								
[x]	REAR BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE							
[x]	REAR DOOR/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE							
[x]	REAR BUMPER/SIDE/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE							
[x]	REAR DOOR/LEFT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)							
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE							
[x]	FRONT MUDGUARD/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)							
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS							
[x]	LIGHTS/RIGHT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)							
ST	ATUS: NOT ACCEPTABLE								

STATUS: NOT ACCEPTABLE

WIND SCREEN

REAR MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE		
	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUI
REAR DOOR/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE		
	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUI
WINDSCREEN/BELOW/LEFT		WINDOW DAMAGE		
	Repair paint - LI	New paint - E	Depr.	Total
3 25 LU =120.00 EUR	0 EUR		50 %	120.00 EUI
FRONT BUMPER/RIGHT/CORNER		SCRATCH WITH PAINT DAMAGE		
	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	211.80 EUR	1	50 %	211.80 EUF
2 0 LU =0.00 EUR	211.80 EUR		50 %	211.80
Number Code	Description	Unit price	Depr.	Total

367.20 EUR

50 %

367.20 EUR



www.vabfleetservices.be Date: 22/09/2017 4/5

1	2	3	4	5	6	7	8	9	10
626.55	211.80	487.20	0	0	0	0	0	0	0
313.28	105.90	243.60	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
1325.55		0	1325.55	0
662.78	NA Deprec.		BG: 0	HOG: 0
	0.00%			
662.78	TOTAL			



www.vabfleetservices.be Date: 22/09/2017 5/5

[x] = Status Modification

Pictures : No CIRCUMS			NORMAL CONCLUSION						
Extra Time :	0 min	Waiting Reason :		in	Towing time : Reason :	0 min			
NOT EXECUTED :	No	•			I				
Remark:	NAVI OK [x]								
Prices in EUR v	vithout VAT								
Authorized by customer :				Executed by VAB	Fleet Services				
Remark authorized	customer :								
Date :	22/09/2017	Hour :	11:26						
Company :									
Executed by VAB F Services	leet								
E-Mail :	@								
Signature authorized	by customer								
-									