

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	140629 KM
File nr. :	1440935	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DOT674 / ZFA25000002164982 /		yr of constructionr :	/
E-File nr. :		First registration :	10/07/2012
VFS-nr. :		Color :	GREY
Make + Model :	FIAT / DUCATO	Fuel type :	DIESEL
Object nr. :	47769	Fuel :	
Classification :	DELIVERY VAN C	Environment Class:	EURO 5
Customer company :	STABILAME SA	Co2:	203g/km
Driver :		Remote controls:	1
Covering :	IMITATION LEATHER	Number keys :	1 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BESTELWAGEN	Engine size:	2999
Gear box :	Manueel	Number of places:	3
Number of gears:	6	Number of doors:	3
HP:	177	kW:	130
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] UNIROYAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] UNIROYAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel FR : [x] UNIROYAL Tyre : [x] OK [x] 2-4/ Rim : / Hubcap :
Wheel RR : [x] UNIROYAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RES: [x] UNIROYAL Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	70	R	15	H
Rear tyre	215	70	R	15	H

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	DENT
[x]	FRONT DOOR/LEFT/CENTER	DENT
[x]	FRONT DOOR/LEFT/FRONT	DENT
[x]	FRONT DOOR/RIGHT/CENTER	DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR LIGHT/LEFT/CORNER	HOLE/CRACK/TORN			
			Repair paint - LI	New paint - E	Depr.
					Total
5	0 LU =0.00 EUR		0 EUR		50 %
[x]	REAR DOOR/CENTER/RIGHT	DENT			VEEL
			Repair paint - LI	New paint - E	Depr.
					Total
4	0 LU =0.00 EUR		226.26 EUR		50 %
					226.26 EUR
[x]	REAR LIGHT/RIGHT/CORNER	HOLE/CRACK/TORN			
			Repair paint - LI	New paint - E	Depr.
					Total
5	0 LU =0.00 EUR		0 EUR		50 %
[x]	REAR DOOR/RIGHT/CENTER	DENT			
			Number	Code	Description
					Unit price
					Depr.
					Total
3	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR	63.00 EUR
[x]	THRESHOLD FRONT/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
6	0 LU =0.00 EUR		232.88 EUR		50 %
					232.88 EUR
[x]	FRONT THRESHOLD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
1	0 LU =0.00 EUR		232.88 EUR		50 %
					232.88 EUR
[x]	WINDSCREEN/BELOW/LEFT	HOLE/CRACK/TORN			
			Repair paint - LI	New paint - E	Depr.
					Total
7	25 LU =120.00 EUR		0 EUR		50 %
					120.00 EUR

[x] FRONT BUMPER/RIGHT/SIDE SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
2	I1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

Accessories and others

[x] OUTSIDE MIRROR RIGHTHAND SIDE WINDOW DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
8	0 LU =0.00 EUR	0 EUR	50 %	

[x] SIDE PROTECTION MISSING/INCOMPLETE

	Repair paint - LI	New paint - E	Depr.	Total
9	0 LU =0.00 EUR	0 EUR	50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
5	1	REAR LIGHT	67.50 EUR	50 %	67.50 EUR

Number	Code	Description	Unit price	Depr.	Total
5	1	REAR LIGHT	67.50 EUR	50 %	67.50 EUR

Number	Code	Description	Unit price	Depr.	Total
7	1	WIND SCREEN	275.40 EUR	50 %	275.40 EUR

Number	Code	Description	Unit price	Depr.	Total
8	1	MIRROR	90.00 EUR	50 %	90.00 EUR

Number	Code	Description	Unit price	Depr.	Total
9	1	SIDE PROTECTION	10.80 EUR	50 %	10.80 EUR

1	2	3	4	5	6	7	8	9	10
232.88	110.64	63.00	226.26	135.00	232.88	395.40	90.00	10.80	0
116.44	110.64	63.00	113.13	67.50	116.44	197.70	45.00	5.40	0

INNOVATIVE	TRADITIONAL	GENERAL	
173.64	1323.22	0	1496.86
HOG: 0	BG: 3		NA Deprec. 835.25
			0.00%
			TOTAL 835.25

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 25/09/2017 Hour : 10:22 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	