

CHO8N1

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	79435 KM
<b>File nr. :</b>	1434559	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1EQR537 / WDD2042001G047029 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	25/02/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	MERCEDES / C	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	BELGACOM INS/FLEET NV	<b>Co2:</b>	133g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE-LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	C BRE 180 CDI BlueEFF. S&S 120PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BREAK	<b>Engine size:</b>	2143
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	120	<b>kW:</b>	88
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>	25/02/2019	<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
		Filled up :	0	

## Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	225	45	R	17	W
Rear tyre	225	45	R	17	W

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	SCRATCH WITH PAINT DAMAGE	
[x]	REAR BUMPER/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	POLIR
[x]	REAR WINDOW/LEFT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR THRESHOLD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	IN
[x]	REAR DOOR/LEFT/CENTER	DENT	
[x]	REAR DOOR/RIGHT/FRONT	DENT	
[x]	FRONT THRESHOLD/LEFT/REAR	CHIPS	IN
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	BOORD DEUR
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT DOOR/RIGHT/CENTER	OTHER DAMAGES	HERSTELD
[x]	FRONT MUDGUARD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT MUDGUARD/LEFT/CENTER	DENT	
[x]	FRONT BUMPER/LEFT	CHIPS	
[x]	FRONT BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	ONDERKANT

## STATUS: NOT ACCEPTABLE

### Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

1	2	3	4	5	6	7	8	9	10
190.00	0	0	0	0	0	0	0	0	0
190.00	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
190.00	0	0	<b>190.00</b>
HOG: 0	BG: 0		NA Deprec. 190.00
			0.00%
			<b>TOTAL 190.00</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 22/09/2017 <b>Hour :</b> 15:39 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	