

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	60350 KM
File nr. :	1440915	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DKE042 / W0LPD8EA3C8092034 /		yr of constructionr :	/
E-File nr. :		First registration :	07/06/2012
VFS-nr. :		Color :	RED
Make + Model :	OPEL / ASTRA BREAK	Fuel type :	DIESEL
Object nr. :	70119	Fuel :	
Classification :	O	Environment Class:	EURO 5
Customer company :	HITOMIZU BVBA	Co2:	109g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	ASTRA BRE ecoFLEX Enjoy FAP 95PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1248
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	95	kW:	70
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	OK [x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/ Hubcap : [x] SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/ Hubcap : [x] SCRATCHED	
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/ Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	15	V
Rear tyre	205	60	R	15	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Interior

- [x] DOOR IN FL OTHER DAMAGES
- [x] DOOR IN FR OTHER DAMAGES

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x]	REAR LIGHT/RIGHT	HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E	Depr.	Total
2	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

[x]	REAR DOOR/CENTER/LEFT	DENT		HAGEL	
		Number	Code	Description	Unit price
0	0				Depr.
					Total

[x]	REAR WINDOW STYLE/CENTER/LEFT/UP	DENT		HAGEL	
		Number	Code	Description	Unit price
0	0				Depr.
					Total

[x]	REAR MUDGUARD/RIGHT/CENTER	DENT		HAGEL	
		Number	Code	Description	Unit price
0	0				Depr.
					Total

[x]	ROOF/CENTER/LEFT	DENT		HAGEL	
		Number	Code	Description	Unit price
0	0				Depr.
					Total

[x]	ROOF STYLE/CENTER/RECHTS	DENT		HAGEL	
		Number	Code	Description	Unit price
0	0				Depr.
					Total

[x]	REAR DOOR/RIGHT/CENTER	DENT		HAGEL	
		Number	Code	Description	Unit price
0	0				Depr.
					Total

[x] FRONT DOOR/RIGHT/CENTER DENT HAGEL

Number	Code	Description	Unit price	Depr.	Total
0	0				

[x] BONNET/CENTER/LEFT DENT HAGEL

Number	Code	Description	Unit price	Depr.	Total
0	0				

[x] FRONT MUDGUARD/RIGHT/CENTER DENT HAGEL

Number	Code	Description	Unit price	Depr.	Total
0	0				

[x] FRONT/LEFT HOLE/CRACK/TORN

	Repair paint - LI	New paint - E	Depr.	Total
1 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	FRONT	28.80 EUR	50 %	28.80 EUR
2	1	REAR LIGHT	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
52.80	114.00	211.80	0	0	0	0	0	0	0
26.40	57.00	105.90	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	378.60	0	378.60
HOG: 0	BG: 0		NA Deprec. 189.30
			0.00%
			TOTAL 189.30

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/09/2017 Hour : 16:40 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	