

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	138820 KM
File nr. :	1441281	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1BGG793 / W0LPD6EG7BG134962 /		yr of constructionr :	/
E-File nr. :		First registration :	24/05/2011
VFS-nr. :		Color :	WHITE
Make + Model :	OPEL / ASTRA	Fuel type :	DIESEL
Object nr. :	47822	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	DALKIA SA<ID>2229924</ID>	Co2:	119g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	ASTRA BER Enjoy DPF 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	No
Variant car:		Engine size:	1686
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner : OK [x]	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel RL : [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel FR : [x] CONTINENTAL Tyre : [x] OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel RR : [x] CONTINENTAL Tyre : OK [x] 4-6/ Rim : / Hubcap : [x] SCRATCHED
Wheel RES: [x] ANDERE Tyre : OK [x] >6/ Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	16	H
Rear tyre	215	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	DENT				
			Repair paint - LI	New paint - E	Depr.	Total
3	15 LU =72.00 EUR		211.80 EUR		50 %	283.80 EUR
[x]	REAR THRESHOLD/RIGHT/FRONT	DENT				
			Repair paint - LI	New paint - E	Depr.	Total
4	10 LU =48.00 EUR		310.50 EUR		50 %	358.50 EUR
[x]	FRONT MUDGUARD/LEFT/CENTER	DENT				
			Repair paint - LI	New paint - E	Depr.	Total
2	10 LU =48.00 EUR		220.18 EUR		50 %	268.18 EUR
[x]	FRONT BUMPER/CENTER/RIGHT	OTHER DAMAGES			AFBLADEREN/HERSTELLING	
	Number Code	Description		Unit price	Depr.	Total
0	0					

Interior

[x]	FLOOR FL	HOLE				
			Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR		0 EUR		50 %	
			Repair paint - LI	New paint - E	Depr.	Total
1	25 LU =120.00 EUR		0 EUR		50 %	120.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR	45.88 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	CARPET	60.00 EUR	50 %	60.00 EUR

1	2	3	4	5	6	7	8	9	10
225.88	268.18	283.80	358.50	0	0	0	0	0	0
135.88	134.09	141.90	179.25	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
45.88	1090.48	0	1136.36
HOG: 0	BG: 0		NA Deprec. 591.12
			0.00%
			TOTAL 591.12

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 22/09/2017 Hour : 12:24 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	