

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: DIRTY [x]
<b>Owner :</b>		<b>Mileage :</b>	107756 KM
<b>File nr. :</b>	1443145	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1HXN333 / WDD2183031A097429 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	22/10/2014
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	MERCEDES / CLS	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	ONBEKEND	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	ONBEKEND	<b>Co2:</b>	135g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	1 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BERLINE	<b>Engine size:</b>	2143
<b>Gear box :</b>	Automaat algemeen	<b>Number of places:</b>	4
<b>Number of gears:</b>		<b>Number of doors:</b>	5
<b>HP:</b>	204	<b>kW:</b>	150
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK [x]	Transport licence :		
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK [x]	Warning triangle :	OK	[x]
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

## Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	285	35	R	18	Y
Rear tyre	285	35	R	18	Y

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

- [x] REAR MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE
- [x] FRONT DOOR/RIGHT/CENTER DENT

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

	Repair paint - LI	New paint - E	Depr.	Total
[x] REAR BUMPER/CENTER/RIGHT HOLE/CRACK/TORN				
2 0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR
[x] FRONT MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE				
1 0 LU =0.00 EUR	264.21 EUR		50 %	264.21 EUR

### Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 5	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		72.90 EUR

1	2	3	4	5	6	7	8	9	10
337.11	254.16	0	0	0	0	0	0	0	0
205.00	127.08	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
72.90	518.37	0	591.27
HOG: 0	BG: 2		NA Deprec. 332.08
			0.00%
			TOTAL 332.08

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 27/09/2017 <b>Hour :</b> 07:28 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b>  	