

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	78091 KM
File nr. :	1442034	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FPQ766 / WDD2042001G207822 /		yr of constructionr :	/
E-File nr. :		First registration :	17/09/2013
VFS-nr. :		Color :	BLACK
Make + Model :	MERCEDES / C BREAK	Fuel type :	DIESEL
Object nr. :	64076	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	GUDRUN NV	Co2:	127g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	C BRE 180 CDI BlueEFF. S&S 120PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	2143
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	120	kW:	88
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	MICHELIN	Tyre :	OK	2-4/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :
Wheel RL :	MICHELIN	Tyre :	OK	2-4/	Rim :		/ Hubcap :
Wheel FR :	MICHELIN	Tyre :	OK	2-4/	Rim :	WHEEL SCRATCHED	/ Hubcap :
Wheel RR :	MICHELIN	Tyre :	OK	2-4/	Rim :	WHEEL SCRATCHED	/ Hubcap :
Wheel RES:	ANDERE	Tyre :	OK	[x] >6/	Rim :		/ Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/ Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/ Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/ Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/ Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/ Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	SCRATCH WITH PAINT DAMAGE
[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/LEFT/CENTER	DENT
[x]	FRONT DOOR/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	WINDSCREEN/CENTER/LEFT	CHIPS
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE

Interior

[x]	SEAT FL	SCRATCHED
[x]	BOOT LID IN	SCRATCHED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR WINDOW/RIGHT	OTHER DAMAGES	KRASSEN IJSKRABBER
		Repair paint - LI	New paint - E
		Depr.	Total
4	25 LU =120.00 EUR	0 EUR	50 % 120.00 EUR
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	
		Repair paint - LI	New paint - E
		Depr.	Total
2	0 LU =0.00 EUR	318.35 EUR	50 % 318.35 EUR
[x]	BONNET/CENTER/RIGHT	OTHER DAMAGES	INWERKING LAK
		Repair paint - LI	New paint - E
		Depr.	Total
1	0 LU =0.00 EUR	290.08 EUR	50 % 290.08 EUR
[x]	ROOF/CENTER/LEFT	OTHER DAMAGES	INWERKING LAK
		Repair paint - LI	New paint - E
		Depr.	Total
1	0 LU =0.00 EUR	481.50 EUR	50 % 481.50 EUR

Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
4	1 WIND SCREEN		367.20 EUR	50 %	367.20 EUR

1	2	3	4	5	6	7	8	9	10
771.58	318.35	285.00	487.20	0	0	0	0	0	0
385.79	159.18	285.00	243.60	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
285.00	1577.13	0	1862.13
HOG: 0	BG: 0		NA Deprec. 1073.56
			0.00%
			TOTAL 1073.56

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 27/09/2017 Hour : 15:53 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	