

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	183525 KM
<b>File nr. :</b>	1440176	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1EAY095 / VF3CC8HR0CT120081 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	08/10/2012
<b>VFS-nr. :</b>		<b>Color :</b>	BLUE D
<b>Make + Model :</b>	PEUGEOT / 208	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	54993	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	FOREM	<b>Co2:</b>	98g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	1 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	208 BER Active 68PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1398
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	5	<b>Number of doors:</b>	5
<b>HP:</b>	68	<b>kW:</b>	50
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	KLÉBER	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RL :	[x]	KLÉBER	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel FR :	[x]	KLÉBER	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RR :	[x]	KLÉBER	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :		

  

[x]	Width	Height	Type	Rim	Index
Front tyre	185	65	R	15	T
Rear tyre	185	65	R	15	T

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT BUMPER/LEFT	SCRATCH WITH PAINT DAMAGE

### Interior

[x]	CENTER CONSOLE	CARVED
[x]	SEAT FL	STAIN
[x]	SEAT REAR RIGHT	CARVED
[x]	LUGGAGE COVER	OTHER DAMAGES
[x]	DOOR IN REAR RIGHT	CARVED

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
1	15 LU =72.00 EUR	241.34 EUR		50 %	313.34 EUR
[x]	FRONT DOOR/RIGHT/CENTER	OTHER DAMAGES		SLECHTE HERSTELLING	
	Number Code	Description	Unit price	Depr.	Total
0	0				

### Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH WITH PAINT DAMAGE			
	Number Code	Description	Unit price	Depr.	Total
2	11 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

### Others

	HUB CAP FL				
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR			50 %	

1	2	3	4	5	6	7	8	9	10
313.34	115.56	0.00	0	0	0	0	0	0	0
156.67	115.56	0.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
115.56	313.34	0	<b>428.90</b>
HOG: 0	BG: 1		NA Deprec. 272.23
			0.00%
			<b>TOTAL 272.23</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 27/09/2017 <b>Hour :</b> 12:52 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b>  	