

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	82720 KM
File nr. :	1440967	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EWM330 / JTDKN36U801617405 /		yr of constructionr :	/
E-File nr. :		First registration :	08/04/2013
VFS-nr. :		Color :	GREY
Make + Model :	TOYOTA / PRIUS	Fuel type :	HYBRID
Object nr. :	36419	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	CLEAR CHANNEL BELGIUM NV	Co2:	92g/km
Driver :		Remote controls:	2
Covering :	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	PRIUS Hybrid Lounge 98PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1798
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	99	kW:	73
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] SEMPERIT Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RL : [x] SEMPERIT Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel FR : [x] SEMPERIT Tyre : [x] OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RR : [x] SEMPERIT Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	45	R	17	Y
Rear tyre	215	45	R	17	Y

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/REAR	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
5	20 LU =96.00 EUR	308.20 EUR		50 %	404.20 EUR
[x]	REAR BUMPER/SIDE/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	REAR DOOR/LEFT/FRONT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
4	40 LU =192.00 EUR	318.35 EUR		50 %	510.35 EUR
[x]	ROOF/CENTER/RIGHT	OTHER DAMAGES		CHEMISCHE INWERKING	
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	FRONT THRESHOLD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE			
	Number Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR
[x]	FRONT MUDGUARD/LEFT/CENTER	OTHER DAMAGES		CHEMISCHE INWERKING	
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

[x]	BONNET/CENTER/LEFT	OTHER DAMAGES	CHEMISCHE INWERKING		
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR

Interior

[x]	FLOOR BOOT	STAIN			
	Number Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	BROKEN / CRACKED			
		Repair paint - LI	New paint - E	Depr.	Total
6	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
6	10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR

Others

RIM FRONT LEFT

	Number Code	Description	Unit price	Depr.	Total
7	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

	Number Code	Description	Unit price	Depr.	Total
7	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

	Number Code	Description	Unit price	Depr.	Total
7	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

	Number Code	Description	Unit price	Depr.	Total
7	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

	Number Code	Description	Unit price	Depr.	Total
6	1 MIRROR		120.00 EUR	50 %	120.00 EUR

1	2	3	4	5	6	7	8	9	10
14.58	991.76	115.56	828.70	616.00	168.00	380.00	0	0	0
14.58	495.88	115.56	414.35	308.00	84.00	380.00	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
510.14	2604.46	0	3114.60
HOG: 0	BG: 0		NA Deprec. 1812.37
			0.00%
			TOTAL 1812.37

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 22/09/2017 Hour : 11:17 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	