

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	109849 KM
File nr. :	1440201	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DTX020 / VF1KZ140647597084 /		yr of constructionr :	/
E-File nr. :		First registration :	27/08/2012
VFS-nr. :		Color :	GREY
Make + Model :	RENAULT / MEGANE BREAK	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KBC BANK NV	Co2:	90g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	MEGANE GT Energy Bose Ed.110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	OK [x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :			
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Interior

[x] SEAT FL OTHER DAMAGES

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/RIGHT/RIGHT DENT 2X

Number	Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

[x] REAR WINDOW/LEFT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	0 EUR		50 %	
4 25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

[x] REAR MUDGUARD/RIGHT/FRONT OTHER DAMAGES

Number	Code	Description	Unit price	Depr.	Total
0	0				

[x] FRONT MUDGUARD/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

[x] FRONT BUMPER/LEFT OTHER DAMAGES

Number	Code	Description	Unit price	Depr.	Total
0	0				

[x] FRONT BUMPER/RIGHT/SIDE SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4 specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		58.32 EUR

HUB CAP FL

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

HUB CAP REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
4	1	BACK WINDOW	250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
58.32	90.00	0	370.00	110.64	431.98	0	0	0	0
58.32	45.00	0	185.00	110.64	215.99	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
168.96	891.98	0	1060.94
HOG: 0	BG: 0		NA Deprec. 614.95
			0.00%
			TOTAL 614.95

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 25/09/2017 Hour : 13:56 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	