

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	162629 KM
<b>File nr. :</b>	1441606	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1DCN044 / VF1KW24B546955423 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	10/04/2012
<b>VFS-nr. :</b>		<b>Color :</b>	WHITE
<b>Make + Model :</b>	RENAULT / KANGOO	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	48582	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	SPIE BELGIUM NV/SA	<b>Co2:</b>	137g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	1 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	KANGOO Authentique FAP 75PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	No
<b>Variant car:</b>	BESTELWAGEN	<b>Engine size:</b>	1461
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	5	<b>Number of doors:</b>	5
<b>HP:</b>	75	<b>kW:</b>	55
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

## Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel RR : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	H
Rear tyre	195	65	R	15	H

Remark :

## Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR BUMPER/SIDE/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/FRONT	DENT

### Interior

[x]	SEAT FL	STAIN
-----	---------	-------

### Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH (WITHOUT PAINT DAMAGE)
-----	-------------------------------	--------------------------------

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR LIGHT/LEFT/CORNER	WINDOW DAMAGE				
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
10	5 LU =24.00 EUR		0 EUR		50 %	24.00 EUR
[x]	REAR BUMPER/RIGHT/CORNER	WINDOW DAMAGE				
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
7	5 LU =24.00 EUR		0 EUR		50 %	24.00 EUR
[x]	REAR MUDGUARD/LEFT/REAR	OTHER DAMAGES			SL HERSTELD	
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
0	0					
[x]	ROOF/REAR/LEFT	OTHER DAMAGES			ROEST	
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
6	I 6	i-vab-ander-01	REPAIR (PER 15')	18.74 EUR		112.44 EUR
[x]	FRONT THRESHOLD/LEFT/FRONT	DENT				
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
5	0 LU =0.00 EUR		232.88 EUR		50 %	232.88 EUR
[x]	FRONT DOOR/LEFT/FRONT	DENT				
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
4	30 LU =144.00 EUR		0 EUR	326.78 EUR	50 %	470.78 EUR

[x]	FRONT THRESHOLD/RIGHT/FRONT		DENT					
			<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>		<b>Total</b>
<b>8</b>	0 LU =0.00 EUR		232.88 EUR			50 %		232.88 EUR
[x]	BONNET/CENTER/LEFT		OTHER DAMAGES					
			<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>		<b>Total</b>
<b>3</b>	0 LU =0.00 EUR		217.56 EUR			50 %		217.56 EUR
[x]	FRONT BUMPER/RIGHT/CORNER		SCRATCH WITH PAINT DAMAGE					
			<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>		<b>Total</b>
<b>2</b>	0 LU =0.00 EUR		158.85 EUR			50 %		158.85 EUR
[x]	REAR DOOR/LEFT/LEFT		OTHER DAMAGES					
			<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>		<b>Total</b>
<b>6</b>	1 6	i-vab-ander-01	REPAIR (PER 15')		18.74 EUR			112.44 EUR

## Interior

[x]	SEAT FR		STAIN					
			<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>		<b>Total</b>
<b>1</b>	1 1	i-vab-rein-07	CLEANING (PER 15')		14.58 EUR			14.58 EUR
[x]	BOOT LID IN		CARVED					
			<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>		<b>Total</b>
<b>1</b>	5 LU =24.00 EUR		0 EUR			50 %		24.00 EUR

## Others

	HUB CAP FR							
			<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>		<b>Total</b>
<b>9</b>	0 LU =0.00 EUR					50 %		

**Pieces**

Number	Code	Description	Unit price	Depr.	Total
1	2	BEKLEDING	25.00 EUR	50 %	50.00 EUR
Number	Code	Description	Unit price	Depr.	Total
4	1	DOOR FL	377.10 EUR	50 %	377.10 EUR
Number	Code	Description	Unit price	Depr.	Total
7	1	REFLEKTOR	20.00 EUR	50 %	20.00 EUR
Number	Code	Description	Unit price	Depr.	Total
9	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
Number	Code	Description	Unit price	Depr.	Total
10	1	REAR LIGHT	67.50 EUR	50 %	67.50 EUR

1	2	3	4	5	6	7	8	9	10
88.58	158.85	217.56	847.88	232.88	224.88	44.00	232.88	22.50	91.50
51.58	79.42	108.78	423.94	116.44	224.88	22.00	116.44	11.25	45.75

INNOVATIVE	TRADITIONAL	GENERAL	
239.46	1922.05	0	<b>2161.51</b>
HOG: 0	BG: 3		NA Deprec. 1200.48
			0.00%
			<b>TOTAL 1200.48</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 26/09/2017 <b>Hour :</b> 15:21 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b>  	