APPRAISAL

COY64Z

[X] EFFECTIVE   [ ] NOT EXECUTED   [X] COLLECTION   [ ] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	108008 KM
File nr. :	1440208	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DHM644 / W0LGM6ELXC1101259 /		yr of constructionr :	/
E-File nr. :		First registration :	21/05/2012
VFS-nr. :		Color :	BLACK
Make + Model :	OPEL / INSIGNIA	Fuel type :	DIESEL
Object nr. :	3779	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	MEDIAHUIS NV	Co2:	116g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	INSIGNIA BER ecofl.Edition S/S DPF 130PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1956
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	131	kW:	96
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

APPRAISAL

Original registr. number :	OK			**Service manual :**	OK	[x]
Cert. of reg. / Part 1:				**Cert. of conformity :**	OK	
Cert. of reg. copy / Part 2:	OK	[x]		**Insurance certificate :**		
Warning vest :	OK	[x]		**Transport licence :**		
Tax certificate :				**Navigation CD/SD/DVD**	OK	[x]
Fuel card :				**Car radio :**	OK	[x]
Mobile phone kit :				**Extinguisher :**	OK	[x]
				Warning triangle :	OK	[x]
First aid kit :	OK	[x]		**Oil level :**	OK	[x]
Jack, wheelspanner :	OK	[x]		**Filled up :**	0	

Wheels and tyres: Summer tires

Wheel			Tyre				Rim		Hubcap
Wheel FL:	[x]	GOODYEAR	**Tyre :**		OK	[x] 2-4 /	**Rim :**	/	**Hubcap :**
Wheel RL :	[x]	GOODYEAR	**Tyre :**		OK	[x] 2-4 /	**Rim :**	/	**Hubcap :**
Wheel FR :	[x]	GOODYEAR	**Tyre :**	[x]	OK	[x] 2-4 /	**Rim :**	/	**Hubcap :**
Wheel RR :	[x]	GOODYEAR	**Tyre :**		OK	[x] 2-4 /	**Rim :**	/	**Hubcap :**
Wheel RES:	[x]	GOODYEAR	**Tyre :**		OK	/	**Rim :**	/	**Hubcap :**

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	W
Rear tyre	225	55	R	17	W

Remark :

Wheels and tyres:

Wheel	Tyre			Rim		Hubcap
Wheel FL:	**Tyre :**	OK	/	**Rim :**	/	**Hubcap :**
Wheel RL :	**Tyre :**	OK	/	**Rim :**	/	**Hubcap :**
Wheel FR :	**Tyre :**	OK	/	**Rim :**	/	**Hubcap :**
Wheel RR :	**Tyre :**	OK	/	**Rim :**	/	**Hubcap :**
Wheel RES:	**Tyre :**	OK	/	**Rim :**	/	**Hubcap :**

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/LEFT/CENTER	CHIPS
[x]	ROOF/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE) POLIEREN
[x]	FRONT DOOR/LEFT/CENTER	CHIPS
[x]	FRONT BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]   REAR MUDGUARD/LEFT/FRONT   SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR

[x]   REAR DOOR/RIGHT/CENTER   SCRATCH WITH PAINT DAMAGE   MEERDERE

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x]   BONNET/CENTER/RIGHT/FRONT   OTHER DAMAGES   CHEMISCHE INWERKING

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR

1	2	3	4	5	6	7	8	9	10
290.08	318.35	308.20	0	0	0	0	0	0	0
145.04	159.18	154.10	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	**916.63**	**0**	**916.63**
HOG: 0	BG: 0		NA Deprec. 458.32
			0.00%
			TOTAL **458.32**

APPRAISAL

[x] = Status Modification

Pictures :   No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time :	0 min	Waiting time :	0 min	Towing time :	0 min
		Reason :		**Reason :**	

NOT EXECUTED :	No
Reason :	
Remark :	

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 25/09/2017 **Hour :** 13:39	
Company :	
Executed by VAB Fleet Services	
E-Mail : @	
Signature authorized by customer	