

www.vabfleetservices.be Date: 29/06/2017 1/4

BQB488

[X] EFFECTIVE [] NOT EXECUTED [] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	32301 KM
File nr. :	1413272	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1LJR083 / VF3LCBHYBFS	248429 /	yr of constructionr :	/
E-File nr. :		First registration :	06/10/2015
VFS-nr. :		Color :	BLACK
Make + Model :	PEUGEOT / 308	Fuel type :	DIESEL
Object nr. :	15193	Fuel:	
Classification:		Environment Class:	EURO 6
Customer company :	VICTORIA BENELUX	Co2:	94g/km
Driver :		Remote controls:	1
Covering:	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan):	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes			
Variant car:	BREAK	Engine size:	1560			
Gear box :	Manueel	Number of places:	5			
Number of gears:	6	Number of doors:	5			
HP:	106	kW:	78			
Fisc HP		Imported vehicle:	No			
Animals transported:	No	Smoked in vehicle:	No			
Due date vehicle inspection:		Extra set of tires:	No			
		Use:	Unknown			
General condition:	General condition:					



www.vabfleetservices.be Date: 29/06/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner:			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre:	OK	[x] 2-4	Rim:		/ Hubcap:	
Wheel RL:	[x]	GOODYEAR	Tyre:	OK	[x] 2-4	Rim:		/ Hubcap:	
Wheel FR:	[x]	GOODYEAR	Tyre: [x]	OK.	[x] 2-4	Rim:		/ Hubcap:	
Wheel RR:	[x]	GOODYEAR	Tyre:	OK	[x] 2-4	Rim:		/ Hubcap:	
Wheel RES:	[x]		Tyre:	OK	/	Rim:		/ Hubcap:	
				1					
		[x]	Width		Height		Type	Rim	Index

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 29/06/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE

[x] FRONT DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

[x] BONNET/CENTER/RIGHT SCRATCH (WITHOUT PAINT DAMAGE) POLIEEREN

STATUS: NOT ACCEPTABLE

Interior

[x] SEAT FL DIRTY

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		14.58 EUR

[x] SEAT REAR L STAIN

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR

1	2	3	4	5	6	7	8	9	10
29.16	0	0	0	0	0	0	0	0	0
29.16	0	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
29.16	0	0	29.16
NA Deprec. 29.16		BG: 0	HOG: 0
0.00%			

TOTAL 29.16



www.vabfleetservices.be Date: 29/06/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMST	TANCES		NORMAL CONCLUSION			
Extra Time :	0 min	Waiting time: 0 m	in	Towing time :	0 min	
		Reason:		Reason:		
NOT EXECUTED:	No			<u> </u>		
Reason:						
Remark:						
Prices in EUR w	ithout VAT					
Authorized by customer :			Executed by VAB Fleet S	Services		
Remark authorized c	oustomer :					
Date :	29/06/2017	Hour: 11:11				
Company :						
Executed by VAB Fle Services	eet					
E-Mail :	@					
Signature authorized b	y customer					