APPRAISAL

CNLZP2

[X] EFFECTIVE   [ ] NOT EXECUTED   [X] COLLECTION   [ ] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	**Cleanliness :**	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		**Mileage :**	122686 KM
File nr. :	1439200	**Mileage start / arrival:**	0 / 0
Reg number / Chassis / Ref :		**Mileag ref. service :**	0
1DWT816 / W0LGT6EL5D1013577 /		**yr of constructionr :**	/
E-File nr. :		**First registration :**	20/09/2012
VFS-nr. :		**Color :**	BROWN D
Make + Model :	OPEL / INSIGNIA	**Fuel type :**	DIESEL
Object nr. :		**Fuel :**	
Classification :		**Environment Class:**	EURO 5
Customer company :	KBC BANK NV	**Co2:**	114g/km
Driver :		**Remote controls:**	2
Covering :	PARTIAL LEATHER	**Number keys :**	2 [x]
Vehicle kind :	VEHICLE	**Seats (minivan) :**	0
Vehicle type :	INSIGNIA BER ecofl.Cosmo S/S DPF 130PK	**Country registration :**	BELGIUM

VAT over the margin - car:	No	**Metallic paint:**	Yes
Variant car:		**Engine size:**	1956
Gear box :	Manueel	**Number of places:**	5
Number of gears:	6	**Number of doors:**	5
HP:	131	**kW:**	96
Fisc HP		**Imported vehicle:**	
Animals transported:		**Smoked in vehicle:**	
Due date vehicle inspection:		**Extra set of tires:**	
		Use:	Unknown

General condition:

APPRAISAL

Original registr. number :	OK			Service manual :	OK	[x]	
Cert. of reg. / Part 1:				Cert. of conformity :	OK		
Cert. of reg. copy / Part 2:	OK	[x]		Insurance certificate :			
Warning vest :				Transport licence :			
Tax certificate :				Navigation CD/SD/DVD			
Fuel card :				Car radio :	OK	[x]	
Mobile phone kit :				Extinguisher :	OK	[x]	
				Warning triangle :	OK	[x]	
First aid kit :	OK	[x]		Oil level :	OK	[x]	
Jack, wheelspanner :				Filled up :	0		

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :		OK	[x]	4-6 /	Rim :		/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :		OK	[x]	>6 /	Rim :		/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6 /	Rim :		/	Hubcap :	
Wheel RR :	[x]	MICHELIN	Tyre :		OK	[x]	>6 /	Rim :		/	Hubcap :	
Wheel RES:	[x]		Tyre :		OK		/	Rim :	[x] MISSING/INCOMPLETE	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	W
Rear tyre	225	55	R	17	W

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/REAR	DENT
[x]	WINDSCREEN/CENTER/RIGHT	WINDOW DAMAGE hersteld
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)

Interior

[x]	SEAT FL	CARVED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]   REAR BUMPER/SIDE/LEFTCENTER   SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x]   REAR MUDGUARD/LEFT/REAR   DENT

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR

[x]   FRONT BUMPER/CENTER/LEFT   DENT

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	520.00	0	0	0	0	0	0	0	0
105.90	260.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	731.80	0		**731.80**
HOG: 0	BG: 0		NA Deprec.	365.90
			0.00%	
			TOTAL	**365.90**

APPRAISAL

[x] = Status Modification

Pictures :   No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time :	0 min	Waiting time :	0 min	Towing time :	0 min
		Reason :		**Reason :**	

NOT EXECUTED :	No
Reason :	
Remark :	

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 20/09/2017 **Hour :** 14:25	
Company :	
Executed by VAB Fleet Services	
E-Mail : @	
Signature authorized by customer	