

CRGWRN

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	132059 KM
File nr. :	1442185	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CUK522 / VF3XS9HM0CZ003803 /		yr of constructionr :	/
E-File nr. :		First registration :	01/03/2012
VFS-nr. :		Color :	WHITE
Make + Model :	PEUGEOT / EXPERT	Fuel type :	DIESEL
Object nr. :	76184	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	CEGELEC INDUSTRY	Co2:	182g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	EXPERT B/F SWB 227 L1H1 FAP(EU5)90PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	No
Variant car:	BESTELWAGEN	Engine size:	1560
Gear box :	Manueel	Number of places:	3
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK			Service manual :	OK	[x]
Cert. of reg. / Part 1:				Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK		[x]	Insurance certificate :		
Warning vest :				Transport licence :		
Tax certificate :				Navigation CD/SD/DVD		
Fuel card :				Car radio :	OK	[x]
Mobile phone kit :				Extinguisher :	OK	[x]
				Warning triangle :	OK	[x]
First aid kit :	OK		[x]	Oil level :	OK	[x]
Jack, wheelspanner :				Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x] 2-4 /	Rim :	/ Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x] 2-4 /	Rim :	/ Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x] OK	[x] 2-4 /	Rim :	/ Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x] 2-4 /	Rim :	/ Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/ Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	65	R	15	H
Rear tyre	215	65	R	15	H

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/LEFT/CENTER DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR LIGHT/LEFT/CORNER HOLE/CRACK/TORN

		Repair paint - LI	New paint - E	Depr.	Total
3	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

[x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

[x] ROOF/CENTER/LEFT OTHER DAMAGES ROEST

		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	361.13 EUR		50 %	361.13 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	REAR LIGHT	67.50 EUR	50 %	67.50 EUR

1	2	3	4	5	6	7	8	9	10
361.13	110.64	91.50	0	0	0	0	0	0	0
180.56	110.64	45.75	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
110.64	452.63	0	563.27
HOG: 0	BG: 3		NA Deprec. 336.96
			0.00%
			TOTAL 336.96

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/09/2017 Hour : 15:35 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	