

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	179535 KM
File nr. :	1440644	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1BWY852 / VF1VY0K0NUC365640 /		yr of constructionr :	/
E-File nr. :		First registration :	23/09/2011
VFS-nr. :		Color :	GREY
Make + Model :	RENAULT / KOLEOS	Fuel type :	DIESEL
Object nr. :	700625	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ORDA-S SA - II	Co2:	174g/km
Driver :		Remote controls:	2
Covering :	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	KOLEOS 4x4 Bose Edition FAP 150PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	150	kW:	110
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] UNIROYAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] UNIROYAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel FR : [x] UNIROYAL Tyre : [x] OK [x] 2-4/ Rim : / Hubcap :
Wheel RR : [x] UNIROYAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	18	Y
Rear tyre	225	55	R	18	Y

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR WINDOW/RIGHT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
1	I1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

[x] REAR DOOR/CENTER/LEFT DENT

	Repair paint - LI	New paint - E	Depr.	Total
4	5 LU =24.00 EUR	301.68 EUR	50 %	325.68 EUR

[x] FRONT DOOR/RIGHT/CENTER DENT

Number	Code	Description	Unit price	Depr.	Total
2	I1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

Accessories and others

[x] OUTSIDE MIRROR RIGHTHAND SIDE SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
3	I1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

1	2	3	4	5	6	7	8	9	10
115.56	63.00	115.56	325.68	0	0	0	0	0	0
115.56	63.00	115.56	162.84	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
294.12	325.68	0	619.80
HOG: 0	BG: 0		NA Deprec. 456.96
			0.00%
			TOTAL 456.96

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/09/2017 Hour : 11:14 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	