

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	88870 KM
File nr. :	1395480	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1KPZ735 / WVWZZZ3CZFE523458 /		yr of constructionr :	/
E-File nr. :		First registration :	12/06/2015
VFS-nr. :		Color :	BLUE
Make + Model :	VOLKSWAGEN / PASSAT	Fuel type :	DIESEL
Object nr. :	701346	Fuel :	
Classification :	C	Environment Class:	EURO 6
Customer company :	KAWASAKI MOTORS EUROPE	Co2:	107g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	150	kW:	110
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
		Filled up :	0	

Wheels and tyres: Winter tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	2-4/	Rim :	/
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	17	M+S
Rear tyre	215	55	R	17	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR WINDOW STYLE/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	SIERLIJST		
		Repair paint - LI	New paint - E	Depr.	Total
2	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
[x]	REAR MUDGUARD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE			
	Number Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	BONNET/CENTER/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		58.32 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	SIERLIJST	20.00 EUR	50 %	20.00 EUR

1	2	3	4	5	6	7	8	9	10
666.75	159.56	0	0	0	0	0	0	0	0
362.54	137.56	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
173.88	652.43	0	826.31
HOG: 0	BG: 0		NA Deprec. 500.10
			0.00%
			TOTAL 500.10

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 04/05/2017 Hour : 16:21 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	