

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	115994 KM
File nr. :	1440078	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FOR160 / WVWZZZ3CZDE030295 /		yr of constructionr :	/
E-File nr. :		First registration :	09/09/2013
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / PASSAT BREAK	Fuel type :	DIESEL
Object nr. :	62458	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	CODITEL BRABANT SPRL	Co2:	122g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	PASSAT VAR Comfortline BMT DSG 105PK Aut	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1598
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :			/	Hubcap :
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	4-6/	Rim :		/	Hubcap :
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	H
Rear tyre	215	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR DOOR/LEFT/CENTER SCRATCH WITH PAINT DAMAGE
- [x] FRONT DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE
- [x] BONNET/CENTER/RIGHT/FRONT CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

- [x] REAR MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE +DEUK

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR

- [x] REAR DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

- [x] REAR THRESHOLD/RIGHT/REAR SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	310.50 EUR		50 %	310.50 EUR

- [x] FRONT DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

Interior

- [x] LUGGAGE COVER MISSING/INCOMPLETE

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR	0 EUR		50 %	

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 6	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		87.48 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
5	1	LUGGAGE COVER	240.00 EUR	50 %	240.00 EUR

1	2	3	4	5	6	7	8	9	10
87.48	95.00	211.80	1255.40	240.00	0	0	0	0	0
87.48	95.00	105.90	627.70	120.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
182.48	1707.20	0	1889.68
HOG: 0	BG: 0		NA Deprec. 1036.08
			0.00%
			TOTAL 1036.08

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 25/09/2017 Hour : 14:30 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	