

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	213934 KM
File nr. :	1444179	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
827BFX / WVWZZZ1EZSK027730 /		yr of constructionr :	/
E-File nr. :		First registration :	19/04/1995
VFS-nr. :		Color :	BLACK
Make + Model :	ONBEKEND / ONBEKEND	Fuel type :	PETROL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	0
Covering :	LEATHER	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:	CABRIOLET	Engine size:	1984
Gear box :	Manueel	Number of places:	4
Number of gears:	5	Number of doors:	3
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
		Filled up :	0	

Wheels and tyres: Winter tires

Wheel FL:	[x]	KLÉBER	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	KLÉBER	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	[x]	KLÉBER	Tyre :	[x]	OK	[x]	4-6/	Rim :		/	Hubcap :
Wheel RR :	[x]	KLÉBER	Tyre :	OK	[x]	4-6/	Rim :			/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	[x]	>6/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	45	R	16	M+S
Rear tyre	205	45	R	16	M+S

Remark : VELGEN NIET ORGINEEL OKK

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR THRESHOLD/RIGHT/FRONT	HOLE/CRACK/TORN
[x]	FRONT DOOR/LEFT/CENTER	DENT
[x]	FRONT DOOR/RIGHT/FRONT	DENT
[x]	LIGHTS/RIGHT/FRONT	CHIPS

Accessories and others

[x]	SIDE PROTECTION	SCRATCH (WITHOUT PAINT DAMAGE)
-----	-----------------	--------------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT MUDGUARD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	5 LU =24.00 EUR	176.14 EUR		50 %	200.14 EUR
[x]	FRONT MUDGUARD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	5 LU =24.00 EUR	176.14 EUR		50 %	200.14 EUR

1	2	3	4	5	6	7	8	9	10
0	200.14	200.14	0	0	0	0	0	0	0
0	100.07	100.07	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	400.28	0	400.28
HOG: 0	BG: 1		NA Deprec. 200.14
			0.00%
			TOTAL 200.14

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 28/09/2017 Hour : 15:00 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	