

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	177465 KM
File nr. :	1440970	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
035APJ / WV1ZZZ2EZ96034514 /		yr of constructionr :	/
E-File nr. :		First registration :	20/05/2009
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / CRAFTER	Fuel type :	DIESEL
Object nr. :	11065	Fuel :	
Classification :		Environment Class:	EURO 4
Customer company :	AQUAFIN NV	Co2:	g/km
Driver :		Remote controls:	2
Covering :	IMITATION LEATHER	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	CRAFTER 35 B/F MWB HR 88pk	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	BESTELWAGEN	Engine size:	2461
Gear box :	Manueel	Number of places:	3
Number of gears:	6	Number of doors:	4
HP:	88	kW:	65
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Winter tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] SEMPERIT Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 2-4/ Rim : / Hubcap :
Wheel RR : [x] SEMPERIT Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RES: [x] MICHELIN Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	235	65	R	16	M+S
Rear tyre	235	65	R	16	M+S

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/CENTER/LEFT	DENT
[x]	REAR DOOR/CENTER/RIGHT	DENT
[x]	FRONT DOOR/LEFT/REAR	DENT
[x]	FRONT DOOR/RIGHT/REAR	DENT
[x]	FRONT DOOR/RIGHT/CENTER	DENT

Interior

[x]	SEAT FL	CARVED
-----	---------	--------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total	
4	0 LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR	
[x]	REAR MUDGUARD/RIGHT/REAR	OTHER DAMAGES		ROEST		
		Repair paint - LI	New paint - E	Depr.	Total	
5	0 LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR	
[x]	REAR DOOR/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total	
6	0 LU =0.00 EUR	238.76 EUR		50 %	238.76 EUR	
[x]	FRONT MUDGUARD/RIGHT/FRONT	DENT				
	Number	Code	Description	Unit price	Depr.	Total
7	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	BONNET/CENTER/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total	
3	0 LU =0.00 EUR	217.56 EUR		50 %	217.56 EUR	

[x]	FRONT/LEFT		DENT		
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	0 EUR		50 %	
[x]	FRONT BUMPER/LEFT		DENT		
		Repair paint - LI	New paint - E	Depr.	Total
1	20 LU =96.00 EUR	0 EUR		50 %	96.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	FRONT BUMPER	302.40 EUR	50 %	302.40 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	FRONT	100.00 EUR	50 %	100.00 EUR

1	2	3	4	5	6	7	8	9	10
398.40	100.00	217.56	231.15	231.15	238.76	63.00	0	0	0
199.20	50.00	108.78	115.58	115.58	119.38	63.00	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	1417.02	0	1480.02
HOG: 0	BG: 3		NA Deprec. 771.51
			0.00%
			TOTAL 771.51

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 25/09/2017 Hour : 13:40 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	