

COWU6B

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	59142 KM
File nr. :	1440172	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1LDJ236 / VNKKD3D370A183093 /		yr of constructionr :	/
E-File nr. :		First registration :	27/08/2015
VFS-nr. :		Color :	SILVER
Make + Model :	TOYOTA / YARIS	Fuel type :	HYBRID
Object nr. :	63522	Fuel :	
Classification :	A	Environment Class:	EURO 6
Customer company :	ELIA ENGINEERING	Co2:	75g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:		Engine size:	1497
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	73	kW:	54
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:			Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	DUNLOP	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RL :	[x]	DUNLOP	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :		
Wheel FR :	[x]	DUNLOP	Tyre :	[x]	OK	[x]	2-4 /	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel RR :	[x]	DUNLOP	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :		
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	H
Rear tyre	195	65	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)

Accessories and others

[x]	DOORHANDLE	SCRATCH WITH PAINT DAMAGE
-----	------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT			SCRATCH WITH PAINT DAMAGE		
			Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR		169.44 EUR		50 %	169.44 EUR
[x]	REAR DOOR/LEFT/FRONT			DENT		
	Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT MUDGUARD/RIGHT/REAR			DENT		
			Repair paint - LI	New paint - E	Depr.	Total
5	10 LU =48.00 EUR		176.14 EUR		50 %	224.14 EUR
[x]	FRONT BUMPER/CENTER/LEFT			SCRATCH WITH PAINT DAMAGE		
			Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR		169.44 EUR		50 %	169.44 EUR

1	2	3	4	5	6	7	8	9	10
0	169.44	63.00	169.44	224.14	0	0	0	0	0
0	84.72	63.00	84.72	112.07	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	563.02	0	626.02
HOG: 0	BG: 1		NA Deprec. 344.51
			0.00%
			TOTAL 344.51

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 25/09/2017 Hour : 12:02 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	