

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	95809 KM
File nr. :	1442592	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FNT387 / WVGZZZ1TZEW018222 /		yr of constructionr :	/
E-File nr. :		First registration :	02/09/2013
VFS-nr. :		Color :	BLUE D
Make + Model :	VOLKSWAGEN / TOURAN	Fuel type :	DIESEL
Object nr. :	3346	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	DELL NV-POBE1626378	Co2:	119g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	TOURAN Highline BMT St/St DSG 105PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	NOK [x]
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x] OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]	MICHELIN	Tyre :	OK	/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	50	R	16	H
Rear tyre	205	50	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE
- [x] REAR DOOR/RIGHT/FRONT DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

Number	Code	Description	Unit price	Depr.	Total
[x] REAR BUMPER/RIGHT/CORNER OTHER DAMAGES BUMPER LOS					
2	I 1 i-vab-ander-01	REPAIR (PER 15')	18.74 EUR		18.74 EUR
[x] REAR DOOR/LEFT/CENTER OTHER DAMAGES					
		Repair paint - LI		Depr.	Total
1	0 LU =0.00 EUR	0 EUR		50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	SIDE PROTECTION PAINTED	100.00 EUR	50 %	100.00 EUR

1	2	3	4	5	6	7	8	9	10
100.00	18.74	0	0	0	0	0	0	0	0
50.00	18.74	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
18.74	100.00	0	118.74
HOG: 0	BG: 0		NA Deprec. 68.74
			0.00%
			TOTAL 68.74

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/09/2017 Hour : 16:14 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	