

www.vabfleetservices.be Date: 21/09/2017 1/4

CPM4SW

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

Commissionar :	KBC REMARKETING	Cleanliness:	INT: VERY DIRTY [x] EXT: CLEAN [x]
Owner:		Mileage :	85409 KM
File nr. :	1440750	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1LDR315 / WVWZZZAUZFW	7312595 /	yr of constructionr :	/
E-File nr. :		First registration :	31/08/2015
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :	59063	Fuel:	
Classification:	E	Environment Class:	EURO 5
Customer company :	VAB RIJSCHOOL NV	Co2:	98g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

Variant car:		Engine size:	1598		
Gear box :	Manueel	Number of places:	5		
Number of gears:	5	Number of doors:	5		
HP:	90	kW:	66		
Fisc HP		Imported vehicle:			
Animals transported:		Smoked in vehicle:			
Due date vehicle inspection:		Extra set of tires:			
		Use:	Unknown		
General condition:		l			

Metallic paint:

Yes



www.vabfleetservices.be Date: 21/09/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest:			Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

		[x] W	idth			Не	eight		Type	Ri	im	Index
Wheel RES:	[x]	CONTINENTAL	Tyre:		OK		/	Rim :		/ Hu	ibcap :	
Wheel RR:	[x]	CONTINENTAL	Tyre:		OK	[x]	2-4 /	Rim:		/ H u	ibcap: [x]	SCRATCHED
Wheel FR:	[x]	CONTINENTAL	Tyre:	[x]	OK	[x]	2-4 /	Rim:		/ H u	ibcap: [x]	SCRATCHED
Wheel RL:	[x]	CONTINENTAL	Tyre:		OK	[x]	2-4 /	Rim:		/ H u	ibcap: [x]	SCRATCHED
Wheel FL:	[x]	CONTINENTAL	Tyre:		OK	[x]	2-4 /	Rim:		/ H u	ibcap: [x]	SCRATCHED

	[x]	Width	Height	Type	Rim	Index
	Front tyre	195	65	R	15	T
	Rear tyre	195	65	R	15	T
_						

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 21/09/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

[x] REAR DOOR/CENTER/LEFT DENT

[x] REAR DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

[x] FRONT DOOR/LEFT/REAR SCRATCH (WITHOUT PAINT DAMAGE)

[x] ROOF/CENTER/LEFT DENT

Accessories and others

[x] OUTSIDE MIRROR RIGHTHAND SIDE SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] FRONT BUMPER/LEFT SCRATCH WITH PAINT DAMAGE

 Repair paint - LI
 New paint - E
 Depr.
 Total

 2 0 LU = 0.00 EUR
 211.80 EUR
 50 %
 211.80 EUR

Others

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	I 2	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		29.16 EUR

1	2	3	4	5	6	7	8	9	10
29.16	211.80	0	0	0	0	0	0	0	0
29.16	105.90	0	0	0	0	0	0	0	0

29.16 211.80 0	
23300	240.96
HOG: 0 BG: 0 NA Deprec.	135.06

0.00%
TOTAL 135.06



www.vabfleetservices.be Date: 21/09/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time :	0 min	Waiting time : Reason :	0 min	Towing time : Reason :	0 min
NOT EXECUTED :	: No				
Reason :					
Remark:					
Prices in EUR v	vithout VAT				
Authorized by customer:			Executed by	VAB Fleet Services	
Remark authorized	customer :				
Date :	21/09/2017	Hour :			
Company :					
Executed by VAB F Services	leet				
E-Mail :	@				
Signature authorized	by customer				
×					