

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	122707 KM
File nr. :	1445137	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ELK010 / YV1FS84A1D2175588 /		yr of constructionr :	/
E-File nr. :		First registration :	14/01/2013
VFS-nr. :		Color :	BEIGE
Make + Model :	VOLVO / S60	Fuel type :	DIESEL
Object nr. :	61120	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	CLINIQUES SAINT LUC ASBL	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	S60 BER D2 Kinetic St/St 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	BERLINE	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	235	45	R	17	Y
Rear tyre	235	45	R	17	Y

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	WINDSCREEN/CENTER/LEFT	CHIPS
[x]	FRONT BUMPER/CENTER/LEFT	CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR WINDOW STYLE/CENTER/LEFT/BELOW	DENT				
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-sp-03	3TH SPOTREPAIR SAME PART	37.44 EUR		37.44 EUR
[x]	FRONT DOOR/LEFT/FRONT	DENT				
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT DOOR/RIGHT/FRONT	DENT				
	Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	BONNET/CENTER/RIGHT	OTHER DAMAGES	CHEMISCHE			
		Repair paint - LI	New paint - E	Depr.	Total	
5	0 LU	=0.00 EUR	290.08 EUR	50 %	290.08 EUR	

Others

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	I 3	personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR		34.41 EUR

RIM FRONT LEFT

	Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

	Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

1	2	3	4	5	6	7	8	9	10
34.41	63.00	63.00	37.44	290.08	380.00	0	0	0	0
34.41	63.00	63.00	37.44	145.04	380.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
577.85	290.08	0	867.93
HOG: 0	BG: 0		NA Deprec. 722.89
			0.00%
			TOTAL 722.89

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/10/2017 Hour : 08:52 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	