

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	90155 KM
File nr. :	1445122	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DVY455 / WBA3D91010F403645 /		yr of constructionr :	/
E-File nr. :		First registration :	13/09/2012
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / 3	Fuel type :	DIESEL
Object nr. :	47250	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ISABEL NV	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	3 BER 316d 116PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : NOK [x] MISSING/INCOMPLETE
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher :
First aid kit :	Warning triangle : OK [x]
Jack, wheelspanner : OK [x]	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel RR : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel RES: [x] ANDERE Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	W
Rear tyre	205	60	R	16	W

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

Conclusion

Bodywork \& windows

[x] FRONT DOOR/LEFT/CENTER OTHER DAMAGES SLECHTE HERSTELLING

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR DOOR/CENTER/RIGHT SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR MUDGUARD/LEFT/CENTER DENT

[x] REAR MUDGUARD/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR DOOR/LEFT/CENTER DENT

[x] FRONT DOOR/RIGHT/REAR SCRATCH (WITHOUT PAINT DAMAGE)

[x] BONNET/CENTER/LEFT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

	Repair paint - LI	New paint - E	Depr.	Total
[x] BONNET/CENTER/LEFT		HOLE/CRACK/TORN	ISOLATIE	
1 2 LU =9.60 EUR	0 EUR		50 %	9.60 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	ISOLATIE	35.00 EUR	50 %	35.00 EUR

1	2	3	4	5	6	7	8	9	10
44.60	0	0	0	0	0	0	0	0	0
22.30	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	44.60	0	44.60
HOG: 0	BG: 0		NA Deprec. 22.30
			0.00%
			TOTAL 22.30

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/10/2017 Hour : 09:12 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	