

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN EXT: CLEAN
<b>Owner :</b>		<b>Mileage :</b>	158652 KM
<b>File nr. :</b>	1445575	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1DEJ491 / WAUZZZ8K4DA048301 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	23/04/2012
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	AUDI / A4 AVANT	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	IDEAL FIBERS & FABRICS WIELSBEKE	<b>Co2:</b>	116g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	2
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	A4 AVANT TDie 136PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BREAK	<b>Engine size:</b>	1968
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	136	<b>kW:</b>	100
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	
<b>General condition:</b>			

Original registr. number : OK	Service manual : OK
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK
Mobile phone kit :	Extinguisher :
First aid kit :	Warning triangle : OK
Jack, wheelspanner : OK	Oil level : OK
	Filled up : 0

## Wheels and tyres: Summer tires

Wheel FL:	PIRELLI	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel RL :	PIRELLI	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel FR :	PIRELLI	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel RR :	PIRELLI	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel RES:	PIRELLI	Tyre :	OK	>6/	Rim :	/	Hubcap :

  

	Width	Height	Type	Rim	Index
Front tyre	225	55	R	16	V
Rear tyre	225	55	R	16	V

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

  

	Width	Height	Type	Rim	Index
Front tyre	0	0		0	
Rear tyre	0	0		0	

Remark :

## Conclusion

### Bodywork \& windows

- [x] BONNET/CENTER/LEFT/FRONT CHIPS
- [x] BONNET/CENTER/RIGHT/FRONT CHIPS
- [x] FRONT BUMPER/LEFT CHIPS
- [x] FRONT BUMPER/RIGHT CHIPS

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

- [x] REAR MUDGUARD/RIGHT/FRONT DENT

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

- [x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE MEERDERE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	0	0	0	0	0	0	0	0	0
105.90	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	211.80	0	<b>211.80</b>
HOG: 0	BG: 0		NA Deprec. 105.90
			0.00%
			<b>TOTAL 105.90</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 09/10/2017 <b>Hour :</b> 11:32 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b>  	